

Cooling Water Pump P-103 - Vibration Follow-up Bulletin

Reference: DEMO-EVT-103-01. Fictional internal demonstration data.

Incident summary

A vibration alert was logged on the P-103 cooling water pump during a night shift. Elevated vibration was reported on the outboard bearing end. Coupling alignment was inspected and found slightly outside tolerance. The pump was returned to service with reduced load and scheduled monitoring.

Follow-up checklist

1. Re-measure vibration on both bearing ends after two operating days.
2. Verify coupling alignment and soft-foot before re-tightening hold-downs.
3. Record suction and discharge pressure during the observation window.
4. Log any recurring vibration events with a new incident reference.

Root cause status

The available evidence is insufficient to confirm a single root cause. Recurring vibration may relate to coupling alignment, bearing condition, or unstable suction conditions; these must be checked together.