Godrej	FIELD REPORT					Document No: Revision No: Effective date:
Location: Complaint Date: Service Date: Service Engineer	BPCL Uran 01-02-202 08-02-2025 Vikrant V.	5	Job Description: Replacement of faulty FRS Con		troller.	
Name (Godrej):		- Alexandra	FRS Device Det	ails		
Data Header		Faulty FRS Devic				lew FRS Device
Make						
Model		UBio - X Face Pro			UBio-X Face Pro	
Date of Manufacturing						
Date of						
Serial No.		AFU130010TBDCG002366			AFU130310TBDLG000647	
Mac Address		00-02-65-23-8E-11			000265251D1B	
Terminal Id		28			28	
Port No.		9003			9003	
Count of added us	ers	1033	1033			
			CHECKPOINT	s		
	Faulty FR	RS Device		New FRS Dev		evice
Check points		Checkmark		Check points		Checkmark
Transfer of Data logs and Templates				Adding of Network Setting		Ø
Device Removal from ALPETA server		Adding System of old Device		Adding System Settin of old Device	gs same as	Ø
Face Authentication Distance				Tranfer of all User Data		8
Terminal id Removal from Network Settings			Count of User device		s of Old	
Port No. removal from Network Settings				Ensure Implementation of Admin id and Password		
User Data Deletion			8	Mounting of device is proper as required at site		
Logs Deletion				Random Physical Check (Users in the userlist should be Authenticated)		
Factory Resetting				Turnstile functionality		
Physical Check (No Authentication permittedafter all data deletion)		8		Mac id binding to L2 switch		
Mac id removal fro	m L2 switch		Y			
Remarks (if any):						
	GODREJ			BPCL Site		
Name	Sulaj Acharya			Biswajit Chowdhury		
Date	08-02-2025			08-02-2025		
	n. Julaj					