


P1
5V
PWMA+
PWMA-
GND
PWMB-
PWMB+
电机控制信号接口
BAT IN 2
SW1
3 BAT+
1 BAT IN
SW-SPDT
定位孔
定位孔
定位孔
定位孔
BAT IN
1
2
焊盘
GND
BAT+
PWMA+ 1
R1
10K
5V 1
R3
10K
U1
IN
INH
SR
IS
VSS
OUT
OUT
GND
BTAN7971B
MOTOR1
U2
VSS
OUT
OUT
GND
IN
INH
SR
IS
BTAN7971B
R2
10K
PWMA-
R4
10K
5V
C2
100nF
R5
510R
R6
470R
R7
470R
R8
510R
C1
100nF
GND
GND
D1
LED
BAT+
R9
电阻
GND
BAT+
PWMB+ 1
R10
10K
5V 1
R12
10K
U3
IN
INH
SR
IS
VSS
OUT
OUT
GND
BTAN7971B
MOTOR2
U4
VSS
OUT
OUT
GND
IN
INH
SR
IS
BTAN7971B
R11
10K
PWMB-
R13
10K
5V
C4
100nF
R14
510R
R15
470R
R16
470R
R17
510R
C3
100nF
GND
GND
BAT+
C5
220UF
C6
220UF
GND


MOTOR2
MOTOR1
1
2
2
1
470R
10K
100nF
10K
510R
510R
10K
100nF
470R
470R
10K
510R
10K
100nF
100nF
10K
510R
470R