Oil Companies International Marine Forum

Revised Ship Inspection Report (SIRE) Programme

Report Number	HCVV-3114-9466-7091
Report Template	VIQ7 - Petroleum (4401)
Vessel Name	SOPHIA
IMO Number	9776559
Date of Inspection	02 Mar 2024
Port of Inspection	Dalian, China
Inspecting Company	INTERNATIONAL MARINE TRANSPORT (IMT)
Selected variants	Crude oil washing
	Inert Gas
	Pumproom
	STS operations

DISCLAIMER

OCIMF DOES NOT WARRANT OPERATOR IDENTITY AND IS NOT RESPONSIBLE FOR THE CHOICE OF SHIPS INSPECTED, THE INSPECTORS CHOSEN, THE PERFORMANCE OF THE INSPECTIONS OR THE CONTENT OF THE REPORTS, OPERATOR COMMENTS AND/OR VPQ RESPONSES DISTRIBUTED UNDER THE REVISED PROGRAMME. OCIMF IS INVOLVED ONLY IN THE RECEIPT, ORGANISATION AND DISTRIBUTION OF THE FOREGOING PROGRAMME OUTPUT. OCIMF DOES NOT REVIEW OR EVALUATE SUCH OUTPUT AND EXPRESSES NO OPINION CONCERNING ITS ACCURACY. WHILE OCIMF MAKES EVERY EFFORT TO ENSURE THAT REPORTS AND OPERATOR COMMENTS ARE RECEIVED, ORGANISED AND DISTRIBUTED IN ACCORDANCE WITH THE SIRE COMPOSITE GUIDELINES OCIMF ACCEPTS NO LIABILITY FOR FAILURE TO DO SO.

Section 1

Chapter 1: General Information

General Information

1.1	Name of the vessel:	SOPHIA
1.2	Vessel IMO Number:	9776559
1.3	Date the inspection was completed:	02 Mar 2024
1.4	Was a full inspection of the vessel completed	Yes
1.5	Port of inspection:	Dalian, China
1.6	Flag:	Greece
1.7	Deadweight: (metric tonnes)	319398.20
	Other Inspector Comments: Vessel was assigned with multiple load lines corresponding to a deadweight of 319398.2mt, 299994.7mt, 284994.7mt, and 259992.0mt respectively. Maximum summer deadweight was in use.	
1.8	Date the vessel was delivered:	03 Jan 2017
1.9	Name of the OCIMF inspecting company:	INTERNATIONAL MARINE TRANSPORT (IMT)
1.10	Date and time the inspector boarded the vessel	02 Mar 2024. 08:30 (UTC +08:00)
1.11	Date and time the inspector departed the vessel	02 Mar 2024. 18:05 (UTC +08:00)
1.12	Time taken for inspection.	9.10
	Other Inspector Comments: 25 minutes was taken for a couple of coffee breaks.	
1.13	Name of the inspector:	For inspecting company only

© Copyright OCIMF 2024

1.14	Is an up to date OCIMF Harmonised Vessel Particulars Questionnaire (HVPQ) maintained and is it readily available?	No
	Other Inspector Comments: The HVPQ 6 report dated 1 March 2024 was reviewed and found that the report contained inaccurate data: - The amount of P&I Cover recorded as a response to Qu 1.1.13.3 was not the same as written in the presented P&I Entry Certificate. - The HVPQ declared a Yes to Qu 1.2.3.4, however the initial CII rating was yet to be verified by a verifier. - The date of expiry of the Safety Construction Certificate entered as a response to Qu 2.1.5 was not the same as presented in the latest safety construction certificate issued on 14 February 2024. - The report declared a Yes to Qu 5.3.8.1, actually the vessel was not provided with a dedicated rescue boat. - The values of test pressure recorded as a response to Qu 6.1.13.2 & 6.1.14.2 were not the same as documented in the latest cargo and bunker piping pressure test reports. - The report declared a Yes to Qu 9.7.3, actually all cargo manifold valves were manual valves. - The HVPQ declared a Yes to Qu 9.16.5, but the inert gas generating space was not fitted with an oxygen alarm. - The TDBF (tail design break force) recorded in Qu 10.1.7 was not the same as entered in the mooring tail certificates.	
1.15	Vessel's operation at the time of the inspection:	Discharging
1.16	Product(s) being handled:	Crude oil
1.17	Vessel type:	Crude/Product Tanker
1.18	Hull type:	Double hull
	Other Inspector Comments: A double hull construction also protected the cargo pump room and oil fuel tanks.	
1.19	Name of the vessel's operator:	MARAN TANKERS MANAGEMENT INC.
1.20	Date the current operator assumed responsibility for the vessel:	03 Jan 2017
1.21	Date of the last port State control inspection:	22 Sep 2023
1.22	Port of the last Port State Control inspection:	Corpus Christi, Texas
	Other Inspector Comments: The last PSC inspection was also a Certificate of Compliance examination by the United States Coast Guard and it had NIL reported deficiency.	
1.23	Name of Classification society:	DNV GL
1.24	Date of expiry of the Class Certificate:	03 Mar 2024
	Other Inspector Comments: The interim Class Certificate and short term Safety Construction Certificate were issued on 14 February 2024 and were valid until 3 March 2024 due to pending completion of Bottom Survey and Bottom Survey Postponement.	

© Copyright OCIMF 2024

1.25	Date of departure from the last class-credited drydock/repair period or in water survey Other Inspector Comments: A class survey statement revealed that the bottom survey was due and was postponed until 11 February 2024 previously but the survey was not completed within the given date due to force major reason. Vessel was issued with an interim class certificate and short term safety construction certificate valid for single voyage till the ship arrive to intended port at China, Dalian in accordance with the Greek Administration's acceptance and letter dated 9 February 2024. The ship was required to undergo a general examination by attending Class Surveyor with satisfactory results to allow the vessel to complete a sighting survey, in order to issue further Interim Class and Safety Construction Certificates align with the postponement of bottom survey for single voyage till Singapore where the In Water Survey can be possible and arranged after cargo discharge operation but not later than 18 March 2024.	11 Jan 2021
1.26	Does the vessel have a recent class Survey Status Report and are past Class Survey Records complete:	Yes

Additional Comments

1.99	Additional Comments During the SIRE Inspection, a DNV Surveyor boarded the vessel and completed the survey for bottom survey postponement. As reported by the master, the new interim class certificate and short term safety construction safety would be issued on 3 March 2024.	

Chapter 2: Certification and Documentation

Certification

2.1.9	What is the vessel's designation as recorded in the IOPP Certificate, Form B, Question 1.11?	4 Crude oil/product carrier
2.2	Is the vessel's P and I Club a member of the International Group?	Yes

© Copyright OCIMF 2024

Crew details on 01 Mar 2024

Officer Crew

										Years in service					
Rank	Watch keeper on this ship?	Nationality	Cert. Comp.	Issuing country	Admin. accept	Tanker cert.	Specialised Tanker Training	Radio qual.	Oper-ator	Rank	Tanker type	All types	Watch	Mo. tour	English prof.
Master	Yes	Greek	Master II/2	Greece	N/A	Oil	Advanced	Yes	15.7	1.6	7.6	7.6	6.6	2.97	Good
Chief Mate	Yes	Greek	Master II/2	Greece	N/A	Oil	Advanced	Yes	6.8	4.2	7.2	7.2	6.1	2.63	Good
2nd Officer	Yes	Greek	OOW (Deck) II/1	Greece	N/A	Oil	Advanced	Yes	7.6	2.7	3.3	3.3	2.7	2.73	Good
2nd Officer	Yes	Greek	OOW (Deck) II/1	Greece	N/A	Oil	Advanced	Yes	8.0	1.8	3.0	3.0	1.8	1.90	Good
3rd Officer	Yes	Filipino	OOW (Deck) II/1	Philippines	Yes	Oil	Advanced	Yes	11.0	1.8	8.4	8.4	1.8	4.63	Good

Engineer Crew

										Years in service					
Rank	Watch keeper on this ship?	Nationality	Cert. Comp.	Issuing country	Admin. accept	Tanker cert.	Specialised Tanker Training	Radio qual.	Oper-ator	Rank	Tanker type	All types	Watch	Mo. tour	English prof.
Chief Engineer	Yes	Greek	Chief Eng III/2	Greece	N/A	Oil	Advanced	N/A	11.3	6.5	17.0	17.0	17.0	1.57	Good
2nd Engineer	Yes	Greek	Chief Eng III/2	Greece	N/A	Oil	Advanced	N/A	2.6	1.3	2.1	2.1	2.1	5.40	Good
3rd Engineer	Yes	Greek	OOW (Eng) III/1	Greece	N/A	Oil	Advanced	N/A	9.6	3.0	3.4	3.4	3.4	7.13	Good
3rd Engineer	Yes	Romanian	OOW (Eng) III/1	Romania	Yes	Oil	Advanced	N/A	9.2	3.5	4.5	4.5	3.5	4.60	Good
4th Engineer	Yes	Filipino	OOW (Eng) III/1	Philippines	Yes	Oil	Advanced	N/A	3.8	0.5	4.9	4.9	0.5	4.63	Good

© Copyright OCIMF 2024

Section 2

Key questions marked Yes without comment.

Chapter 2: Certification and Documentation

Safety Management and the Operators Procedures Manuals

2.3

Survey and Repair History

2.7

Anti Pollution

2.10, 2.12, 2.14

Chapter 3: Crew Management

Crew Management

3.4

Crew Qualifications

3.5, 3.6

Chapter 4: Navigation and Communications

Policies, Procedures and Documentation

4.1, 4.2, 4.4, 4.6

Navigation Equipment

4.7, 4.10, 4.11, 4.14, 4.16, 4.18, 4.20

Communications

4.22, 4.24, 4.25, 4.26, 4.27

Chapter 5: Safety Management

Safety Management

5.2, 5.5, 5.6, 5.10, 5.11

Drills, Training and Familiarisation

5.12, 5.14, 5.15

© Copyright OCIMF 2024

Enclosed Space and Pump Room Entry Procedures:

5.16, 5.18, 5.20

Monitoring Non-Cargo Spaces:

5.22

Hot Work Procedures

5.25, 5.26

Life Saving Equipment

5.27, 5.28, 5.31, 5.32

Fire Fighting Equipment

5.34, 5.35, 5.36, 5.37, 5.38, 5.41, 5.44

Material Safety Data Sheets (MSDS)

5.46

Sample Arrangements

5.48

Chapter 6: Pollution Prevention

Pollution Prevention

6.1, 6.2

Cargo Operations and Deck Area Pollution Prevention

6.6, 6.8, 6.9

Pump Rooms and Oil Discharge Monitors

6.12

Engine and Steering Compartments

6.15, 6.16, 6.18, 6.20

Ballast Water Management

6.22

Chapter 7: Maritime Security

© Copyright OCIMF 2024

Policies and Procedures

7.1, 7.2, 7.3, 7.4, 7.6, 7.7, 7.8, 7.9, 7.10, 7.11

Cyber Security

7.14, 7.16

Chapter 8: Cargo and Ballast Systems - Petroleum

Policies, Procedures and Documentation

8.1, 8.2

Stability and Cargo Loading Limitations

8.6

Cargo Operations and Related Safety Management

8.7, 8.10, 8.13

Ullaging, Sampling and Closed Operations

8.16, 8.17, 8.18

Venting Arrangements

8.20, 8.21

Inert Gas System

8.24, 8.25, 8.27, 8.28

Crude Oil Washing

8.32, 8.33, 8.35, 8.36

Manifold Arrangements

8.42, 8.43

Pump Rooms

8.44, 8.47, 8.48

Cargo Lifting Equipment

8.50

Ship to Ship Transfer Operations

8.51, 8.53

Chapter 9: Mooring

© Copyright OCIMF 2024

Mooring Equipment Documentation and Management

9.1, 9.2, 9.3, 9.5, 9.6, 9.7

Mooring procedures

9.10, 9.11, 9.13

Mooring equipment

9.14, 9.15, 9.17, 9.18, 9.19

Anchoring equipment

9.20, 9.21, 9.22, 9.23

Single Point Moorings

9.25

Emergency Towing Arrangements

9.28, 9.29

Chapter 10: Engine and Steering Compartments

Policies, Procedures and Documentation

10.1, 10.3, 10.4, 10.5, 10.6, 10.8, 10.9

Planned Maintenance

10.13

Safety Management

10.14, 10.15, 10.17

Fire Fighting Equipment

10.18, 10.20, 10.24, 10.25, 10.26, 10.27, 10.28, 10.29, 10.31

Machinery Status

10.33, 10.35, 10.37

Steering Compartment

10.40, 10.41, 10.42, 10.43

Chapter 11: General Appearance and Condition

© Copyright OCIMF 2024

Hull, superstructure and external weather decks

11.1, 11.2, 11.3, 11.4, 11.5, 11.6, 11.7, 11.8

Electrical Equipment

11.10, 11.11

Internal Spaces

11.12

Accomodation Areas

11.13, 11.14, 11.15, 11.16

© Copyright OCIMF 2024

Section 3

Chapter 2: Certification and Documentation

Certification

2.1 Are all the statutory certificates listed below, where applicable, valid and have the annual and intermediate surveys been carried out within the required range dates? Y N NS NA

Other Inspector Comments: The safety construction certificate was short term and was valid until 3 March 2024.

Safety Management and the Operators Procedures Manuals

2.4 Does the Operator's representative visit the vessel at least bi-annually? Y N NS NA

Other Inspector Comments: The last visit was made by a technical superintendent between 19-21 October 2023, and the visit previous to that was made by a marine superintendent on 15-17 October 2023.

2.5 Is a recent operator's internal audit report available and is a close-out system in place for dealing with non-conformities? Y N NS NA

Other Inspector Comments: The last annual internal audits (ISM / ISPS / MLC) were carried out on 1 and 14 November 2023. Nil audit findings were on reported.

2.6 Does the Master review the safety management system, report to the operator on any deficiencies and does the operator respond to the Master's review? Y N NS NA

Other Inspector Comments: Company's procedures required the Master to review the Safety Management System (SMS) at least once during his service contract on board. The last master's SMS review was reported by the previous master on 14 November 2023. Reviews with feedback from the operator were available.

© Copyright OCIMF 2024

Survey and Repair History

2.8	Has the vessel been enrolled in a Classification Society Condition Assessment programme (CAP)? Other Inspector Comments: Vessel was less than 15 years old.	Y	N	NS	[NA]
2.9	Are procedures in place to carry out regular inspections of cargo and ballast tanks, void spaces, trunks and cofferdams by the vessel's personnel and are records maintained? Other Inspector Comments: As per the company's procedures, the frequency of inspection of cargo tanks was 30 months (+/- 6 months). For ballast tanks, void spaces and cofferdams, the frequency was 6 months. All cargo tanks (including two slop tanks) were internally inspected by the ship's crew between 27-28 December 2020. According to the PMS (Planned Maintenance System), a 24-month postponement of cargo tank inspections beyond the 36 months until 27 December 2025 was approved by the operator. Ballast tanks were inspected on 27-28 November 2023. Tank inspection reports were reviewed at random and recorded in good condition with no structural deterioration/deformity and protective coatings were intact.	[Y]	N	NS	NA

Anti Pollution

2.11	If the disposal of engine room oily water or sludge to a cargo or slop tank has taken place, has the event been recorded in both Oil Record Books, was the receiving tank free of cargo and have the transfer arrangements been approved as per IOPP Form B? Other Inspector Comments: Engine room bilge water and sludge could be transferred to a port (P) or starboard (S) slop tank by means of non-permanent connection. However, there was no such transfer on record in the previous 12 months.	Y	N	NS	[NA]
2.13	Is the vessel provided with an approved Ballast Water and Sediments Management Plan, are records maintained of all ballast water exchanges or treatment operations and are the officers aware of BWM requirements? Other Inspector Comments: Vessel was certificated to comply with ballast water discharge standard in accordance with regulation D-2 (treatment). The ship maintained a ballast water log book to record ballast water movements (uptake, treatment and discharge).	[Y]	N	NS	NA

© Copyright OCIMF 2024

Structure

2.15 Is the vessel free of any documentary or visual evidence to indicate any structural concerns? Y N NS NA

Other Inspector Comments: Condition Evaluation report stated that the first Special Survey was completed on 5 December 2021. A close-up examination of several cargo and ballast tanks was completed. Coatings of all cargo and ballast tanks were reported in good condition. No tank repair was on record.

2.16 If any cargo / ballast tanks, void or hold spaces were sighted from the deck, were they in good order, free from oil contamination and could the vessel easily check or sample segregated ballast prior to deballasting? Y N NS NA

Other Inspector Comments: Ballast tank's internals could be quickly checked by opening the sample port. No.3 (S) and No.4 (S) ballast tanks were sighted through the tank access hatch dome from the main deck and found free from oil contamination. Hard coatings of visible areas appeared to be in good condition with little evidence of minor coating damages.

Additional Comments

2.99 Additional Comments

Chapter 3: Crew Management

© Copyright OCIMF 2024

Crew Management

3.1 Does the manning level meet or exceed that required by the Minimum Safe Manning Document? Y N NS NA

Other Inspector Comments: Vessel's Minimum Safe Manning Certificate stipulated a crew of 12 (periodically unattended machinery space) that consisted of 4 Deck Officers including a master and chief officer, 3 Engineer Officers including a chief engineer and second engineer, 1 Boatswain (STCW II/5), and 4 Able Seamen (STCW II/5). The actual manning exceeded the required manning level by 1 Deck Officer, 2 Engineer Officers, 1 Electrician, 1 Trainee Electrician, 1 Able Seaman, 1 Ordinary Seaman, 2 Wipers, 1 Cook, and 2 Messmen.

3.2 Are the STCW and flag Administration's regulations that control hours of work to minimise fatigue being followed and are all personnel maintaining hours of rest records in compliance with MLC or STCW requirements? Y N NS NA

Other Inspector Comments: Daily hours of rest were maintained through a computer program that automatically checked compliance with work and rest hours legislation. Cross checking indicated that records were accurate.

3.3 Are all personnel able to communicate effectively in a common language? Y N NS NA

Other Inspector Comments: English was the common working language on board. Greek was also speaking among Greek crews.

Crew Qualifications

3.7 If the vessel is equipped with an Electronic Chart Display and Information System (ECDIS) have the Master and deck officers undertaken both, generic training and type-specific familiarisation on the system fitted onboard? Y N NS NA

Other Inspector Comments: Master and deck officers had received generic ECDIS training and certification as well as computer based ECDIS type-specific training. All deck officers were required to complete an ECDIS familiarization check-list on joining the vessel.

© Copyright OCIMF 2024

Drug and Alcohol Policy

3.8 Does the operator have measures in place to prevent Drug and Alcohol abuse in accordance with OCIMF guidance?

Y | N | NS | NA

Other Inspector Comments: Consumption of alcohol (only beer) was controlled by the master and was limited to a maximum one can of beer per person per day at sea. No alcohol consumption was allowed on board when the ship was in port or at anchor. Drug and alcohol tests of the ship's crew were recorded:
(1) 5 February 2024: Monthly random alcohol breathalyser test of all crew members at master's discretion.
(2) 14 December 2023: Quarterly unannounced alcohol test of at least 25% of fleet vessels Masters along with a minimum 4 crew members initiated by the operator.
(3) 31 March 2023: Annual unannounced drug & alcohol testing of all ranks on board by an external agency.

Additional Comments

3.99 Additional Comments

A total of five crew members (including a junior engineer) were relived at the time of the inspection. The on-signing crew joined the vessel on the evening of 1 March 2024.

Chapter 4: Navigation and Communications

© Copyright OCIMF 2024

Policies, Procedures and Documentation

4.3 Are procedures in place for the testing of bridge equipment before arrival / departure and check-lists in effective use for pre-arrival, pre-departure, watch handover and master-pilot exchange?

Y | N | NS | NA

Other Inspector Comments: Please refer to the observation under VIQ Ref. 4.9.

4.5 Are the deck officers' familiar with the operators Under Keel Clearance policy, able to demonstrate satisfactory UKC calculations for the last voyage and is the policy comprehensive?

Y | N | NS | NA

Other Inspector Comments: Operator's under keel clearance (UKC) policy required vessels to maintain a minimum UKC as below instructions:
(a) During transits of the Malacca and Singapore Straits:
- 3.5 meters at static draught & 15% of the deepest draught including any provisions for hogging and sagging always comply with both rules.
- For eastern bank (Horsburgh Lighthouse), 4.0 meters at static draft & 20% of the deepest draft including any provisions for the hogging and sagging always comply with both rules.
- CATZOC factor need not be applied.
(b) Open Sea in Shallow waters - 20% of the deepest draught including any provisions for the hogging and sagging.
(c) Open Sea in Deep waters - 20% of vessel's breadth.
(d) Fairways and port approach including unprotected anchorage or when moored on SBM/CBM in open sea - 15% of the deepest draught including any provisions for the hogging and sagging.
(e) Inside ports/ Channels/ Canals and SBM/CBM in sheltered waters - 10% of the deepest draught including any provisions for the hogging and sagging.
(f) Whilst moored including protected anchorage - 10% of the deepest draught including any provisions for the hogging and sagging which can be reduced to 1.5% of vessel's breadth after exception from operation department.
(g) Anchored in open sea at un-protected waters - 15% of the deepest draft including any provisions for the hogging and sagging but not less than 3.0 meters.
(h) Anchored in protected waters - 10% of the deepest draft including any provision for the hogging and sagging but not less than 2.0 meters.

Category Zone of Confidence (CATZOC) was considered for calculating the UKC except for Malacca and Singapore Straits transiting.

Navigation Equipment

4.8 Are navigation lights in good order, the OOW aware of the procedures for testing the lights and actions in event of failure?

Y | N | NS | NA

Other Inspector Comments: The 2nd officer (A) demonstrated a satisfactory test of the navigation light failure alarm.

4.9 Are the Standard Magnetic and Gyro compasses in good order and is the OOW aware of the requirements for taking compass errors and is the compass error book maintained.

Y | N | NS | NA

© Copyright OCIMF 2024

Inspector Observations: The standard magnetic compass was observed with a big bubble (approximately 20 mm in size) in the liquid-filled capsule, indicating a potential leaking from the capsule. The checklist for pre-arrival of the current port didn't contain any remark to the magnetic compass.

Initial Operator Comments: While on the bridge,

- *The calculated deviation figures, on all headings, noted to be broadly agreed with the deviation card. Compass Error Book, pre-arrival checklists and bridge logbook cross-checking were found to be free of any inconsistency.*
- *Vessel's both gyro compasses were noted being fully operational.*

The Spare Magnetic compass bowl was noted operational and free of air bubbles, movements of the compass card were adequate.

Corrective Action:
Before inspection was completed, the magnetic compass bowl was on the top of the wheelhouse, and in line with the maker's recommendations, the bubble removal took place through the filler hole, the fluid liquid was added, and confirmed to be free from any air bubbles, effected.
Action completed on: March 4th, 2024.

Preventive Action:
-Inspection findings included in 03/2024 Fleet Notice.
-A job order (156-24-004) was created in the e-Outstanding Management System platform
-On the 4th of March, onboard training for all bridge officers was delivered by the Master. This was recorded in SMS form C036 – Vessels Personnel Training.

4.12 Is there an effective Chart and Publication (Paper and Electronic) Management System in place and are the deck officer's familiar with the process including the effective management of T and P notices? [Y] N NS NA

Other Inspector Comments: ECDIS was supplied with official Electronic Navigational Charts (ENCs) and its chart database was updated to Notice to Mariners Week 09/2024 (29 February). Updates (including AIO updates) to ECDIS chart database were being distributed weekly through online communications. Admiralty Digital Publications and Admiralty e-Nautical Publications were installed on two independent desktop computers and were updated weekly.

4.13 Are deck officers aware of the requirements for managing Navtex and Navarea Warnings and is there evidence of an effective system in place to monitor these warnings? [Y] N NS NA

Other Inspector Comments: Navtex warnings were displayed directly in the ECDIS unit and reported double checked by duty officers. Random checks of the latest Navtex and Navarea warnings were made and relevant warnings were plotted.

4.15 Is the master and deck officers' familiar with the safety parameter settings for the ECDIS and have the safety settings been correctly applied for the vessels passage? [Y] N NS NA

© Copyright OCIMF 2024

Other Inspector Comments: Safety parameter settings were established during the entire voyage as per company policy. Random checks with the attending deck officers indicated that they were familiar with related company policy for safety parameters including Safety Contour / Safety depth / Safety frame.

4.17 Are the master and deck officers aware of the requirements of Electronic Chart Display and Information System (ECDIS) and does the system fitted meet SOLAS and flag state requirements? [Y] N NS NA

Other Inspector Comments: ECDIS was the sole means of navigation. Additionally, the vessel had one laptop equipped with software that could emulate full ECDIS functionality. Ship's officers could view the licensed ENCs on the laptop in case of ECDIS system failure.

4.19 Is the master and deck officers aware of the requirements for the echo sounder and is there evidence that it has been in use as appropriate during the voyage? [Y] N NS NA

Other Inspector Comments: The echo sounder displayed depth below Keel Fore & Aft at the same time, and a printer was connected. At the time of the inspection, the depth alarm was checked by the 2nd officer (B) and found in order.

Communications

4.21 Are deck officers' familiar with the preparation and transmission of distress and urgency messages on the GMDSS equipment, are instructions clearly displayed and equipment in good order? [Y] N NS NA

Other Inspector Comments: GMDSS Equipment operating instructions were clearly posted at the operating station. During the inspection, the 2nd officer (A) demonstrated a satisfactory understanding of the operations of equipment and communications in case of emergencies.

4.23 Are the officers aware of the periodical test requirements for GMDSS equipment and is the radio logbook correctly maintained with entries of such tests? [Y] N NS NA

Other Inspector Comments: Daily, Weekly and monthly entries were duly logged down with Master's signature on a daily basis.

© Copyright OCIMF 2024

Additional Comments

4.99 Additional Comments

An anemometer display and monitoring repeater with a printer was provided in the cargo control room (CCR) and it was able to give audible and visual alarms when exceeding two desired wind speed limits.

Chapter 5: Safety Management

Safety Management

5.1 Are officers' familiar with the process for conducting Risk Assessments for routine and non-routine tasks, do operators provide adequate procedures for conducting RA and is there sufficient evidence of this process undertaken? Y N NS NA

Other Inspector Comments: Risk Assessment library and procedures were available for review. Generic Risk Assessments were provided. The chief officer was found familiar with the procedures.

5.3 Is the appointed Safety Officer suitably trained, aware of his responsibilities and is there evidence to show that the safety officer has been effectively performing duties associated with this role? Y N NS NA

Other Inspector Comments: The chief officer was the appointed Safety Officer and he had a certificate for classroom Safety Officer training. He also had certificates for attending the Risk Assessment training, Accident and Incident investigation.

5.4 Are the ship's officers able to demonstrate their familiarisation with the operation of fixed and portable firefighting, lifesaving and other emergency equipment? Y N NS NA

Other Inspector Comments: Following equipment was checked/tested satisfactorily during this inspection: Main and emergency fire pumps, emergency steering gear and self-contained breathing apparatus (SCBA).

5.7 Are crew members participating in safety meetings and is there evidence of effective discussions on safety related issues with shore management feedback? Y N NS NA

Other Inspector Comments: Safety Committee Meetings were carried out at monthly intervals. Operator's responses were available with comments and suggestions. Last safety meeting was held on 30 January 2024.

5.8 Are the crew aware of the requirements for reporting of accidents, incidents, non-conformities and near misses and is there an effective system of reporting and follow up investigation in Y N NS NA

© Copyright OCIMF 2024

place?

Other Inspector Comments: On average, the vessel reported 3-4 near misses per month through the electronic reporting system. Stop work cards were also given. No incident was on record since the last internal audit.

5.9 Are the officers and ratings aware of the requirements of the ISGOTT Ship/Shore Safety Check List (SSSCL) and are the provisions of the check list being complied with? Y N NS NA

Other Inspector Comments: Repetitive checks to confirm continued compliance with SSSCL requirements were recorded every 4 hours. The 2nd officer (B) was interviewed and found aware of the contents and use of the document.

Drills, Training and Familiarisation

5.13 Are the crew familiar with their duties in the event of an emergency and are emergency drills being carried out as required? Y N NS NA

Other Inspector Comments: Mandatory emergency drill plans and annual shipboard emergency drill plans for the year 2024 were available for review. Drills were carried out according to the plans. The enclosed space entry and rescue drill was performed on 20 January 2024 and the pollution clean-up drill was conducted on 17 January 2024.

Enclosed Space and Pump Room Entry Procedures:

5.17 Are the crew aware of safe entry procedures into the pump room, compressor rooms and trunk spaces as applicable and are safe entry procedures being followed? Y N NS NA

Other Inspector Comments: An authorised pump room (P/R) entry permit was posted on the P/R entrance, and a log of persons entering was maintained. In addition to the fixed gas detection systems, a portable multi-gas detector was placed at the entrance to the P/R, with its sampling tube extending down to the P/R bottom. Two ventilation fans were running. Personal multi-gas detector was worn as well.

5.19 Are the officers aware of the correct settings of pump room fire and flooding dampers and are the dampers clearly marked and in good order? Y N NS NA

Other Inspector Comments: During the inspection, the remote operation of both flooding dampers (P&S) was tried out by the ship's staff and found satisfactory.

© Copyright OCIMF 2024

Monitoring Non-Cargo Spaces:

5.21 Are spaces adjacent to cargo tanks, including pipe ducts, regularly monitored for accumulations of gas with an operable fixed and / or portable measuring equipment? [Y] N NS NA

Other Inspector Comments: A permanent combustible gas detection system was capable of sampling the fore peak void tank, ballast tanks adjacent to cargo tanks, inert gas mainline and detection system cabinet on a rotational basis. At the time of the inspection, more than 50% of ballast tanks were loaded with water and they were isolated from the detection system to avoid ingress of seawater in the sampling lines and sampling pumps of the system.

Gas Analysing Equipment

5.23 Does the vessel have appropriate duplicate portable gas detection equipment suitable for the cargoes carried, are the officers' familiar with the operation, calibration and is the equipment being maintained in accordance with manufacturers and industry recommendations? [Y] N NS NA

Other Inspector Comments: As per the records on board, all portable and personal gas detectors were subjected to a bi-annual calibration check and pre-use bump test by the ship's staff. Sufficient stock of span gas, calibration kit components, and toxic gas tubes were provided. The chief officer demonstrated a successful calibration of a portable multi-gas detector at the time of the inspection.

Hot Work Procedures

5.24 Are officers aware of the requirements for hot work and are hot work procedures in accordance with the recommendations of ISGOTT and OCIMF guidelines? [Y] N NS NA

Other Inspector Comments: The 2nd engineer well explained hot work procedures during the interview. Company approval was required and senior officers were required to be involved in any hot work conducted outside of the engine room workshop.

© Copyright OCIMF 2024

Life Saving Equipment

5.29 Are lifeboats, including their equipment and launching mechanisms, in good order and have they been launched and manoeuvred in the water in accordance with SOLAS requirements? [Y] N NS NA

Other Inspector Comments: Port and starboard lifeboats' engine, lights, air supporting system, rudder movement and equipment were checked at random and found satisfactory. Both lifeboats were launched and manoeuvred in water on 2 January 2024.

5.30 Is the rescue boat, including its equipment and launching arrangement, in good order and officers' familiar with the launch procedures? [Y] N NS NA

Other Inspector Comments: The port lifeboat was designated as the rescue boat. Procedures for recovery of the boat from water were available and posted on site.

5.33 Are immersion suits in a good order, correctly positioned and officers aware of maintenance and carriage requirements? [Y] N NS NA

Other Inspector Comments: The bosun was found familiar with donning and use of the immersion suit. Periodical service by an authorised person was within the expiry date. Last service was recorded on 4 December 2021.

© Copyright OCIMF 2024

Fire Fighting Equipment

5.39 Are officers aware of the requirements for testing fixed fire detection and alarm systems and are the systems in good order and tested regularly? Y N NS NA

Other Inspector Comments: Fire detectors and manual call points were tested in a phased manner. Appropriate test kits and past test records were sighted.

5.40 Are the crew familiar with the fixed fire extinguishing systems, where fitted, are they in good order and are clear operating instructions posted? Y N NS NA

Other Inspector Comments: The 2nd engineer well explained how to operate the machinery space water mist fire fighting and foam fire extinguishing systems in case of emergency.

5.42 Are portable fire extinguishers in good order with operating instructions clearly marked and are crew members familiar with their operation? Y N NS NA

Other Inspector Comments: Annual and monthly shipboard inspection records were available. The cook was familiar with the use of the portable CO2 and dry powder fire extinguishers in the galley.

5.43 Are crew members familiar with donning breathing apparatus and are Fireman's Outfits in good order and ready for immediate use? Y N NS NA

Other Inspector Comments: The 2nd engineer and bosun were found familiar with donning procedures and pre-use tests. SCBA sets were randomly checked, and the air bottle low-level alarm was tested satisfactorily. Compressor air quality test was recorded on 22 September 2023.

5.45 Are fire flaps clearly marked to indicate the spaces they serve and is there evidence of regular testing and maintenance? Y N NS NA

Other Inspector Comments: During the inspection, the engine room funnel flap louvres and air ventilation fire flaps (No.2 & No.4) were checked by the ship's engineers and found to close completely.

© Copyright OCIMF 2024

Access

5.47	Is the vessel provided with a safe means of access and are all available means of access (gangway / accommodation ladder / pilot ladder / transfer basket) in good order and well maintained? Other Inspector Comments: Inspector boarded the vessel by shore gangway while the ship was port side alongside for discharge.	Y	N	NS	NA

Additional Comments

5.99	Additional Comments	

Chapter 6: Pollution Prevention

Pollution Prevention

6.3	Are means readily available for dealing with small oil or chemical spills? Other Inspector Comments: A pneumatic driven pump was positioned at each side on the aft end of the cargo area. The flexible discharge pipe from each pump was led to a slop tank. The starboard pump was tested and found ready for immediate use.	Y	N	NS	NA

© Copyright OCIMF 2024

Cargo Operations and Deck Area Pollution Prevention

6.4	Are Annex 1 and 2 overboard valves and cargo system sea valves suitably secured, thoroughly checked closed prior to commencement of cargo transfer and where provided, sea valve-testing arrangements in order and regularly monitored for leakage? Other Inspector Comments: Cargo system sea and overboard pipeline valves were shut, sealed and the lines were blanked. Spool piece as the emergency connection between the cargo and ballast system was noted removed. The cargo sea chest integrity was to be checked by air pressure testing when the ship was anchored or moored alongside a berth - last such check was performed on 15 January 2024.	[Y]	N	NS	NA
6.5	If ballast lines pass through cargo and/or Bunker tanks are they tested regularly, and the results recorded?	Y	N	NS	[NA]
6.7	Have bunker pipelines been satisfactorily tested on an annual basis and is there suitable evidence of this test? Other Inspector Comments: The last hydrostatic pressure test of bunker lines (HFO & MGO) was carried out on 28 February 2024 to 4.5 bars (100% of their rated working pressure). They were also pressure tested to 6.75 bars on 26 June 2023.	[Y]	N	NS	NA
6.10	Are the arrangements for the disposal of oily water in the forecastle and other internal spaces adequate and are officers aware of these requirements? Other Inspector Comments: A water-driven ejector was provided for pumping out forecastle bilges and overboard valves were shut and lashed and warning notices were posted in the vicinity of the valve. The starboard bilge high level alarm was tried out and found satisfactory.	[Y]	N	NS	NA

© Copyright OCIMF 2024

Pump Rooms and Oil Discharge Monitors

6.11 Are pump room / trunk space bilge high level alarms fitted, regularly tested and the results recorded? [Y] N NS NA

Other Inspector Comments: P/R bilge high level alarms were to be tested monthly or prior to any cargo operation. The starboard bilge alarm was tested and found in working order.

6.13 If an ODME is fitted, is it in good order, well maintained and any operational downtime recorded in the ORB? [Y] N NS NA

Other Inspector Comments: Records indicated that the ODME were tested in simulation mode every month with no defective signs. Last simulation test was dated 10 February 2024. The ODME system was also checked, calibrated and tested by service technicians on 1 January 2023.

Engine and Steering Compartments

6.14 Are the engine room bilge oily water pumping and disposal arrangements in good order? [Y] N NS NA

Other Inspector Comments: The engine room bilge oily water pumping and disposal arrangements were identified and secured to prevent accidental opening.

6.17 Is the oily water separator in good order, free from unauthorised modifications and are the engineers well familiar with its operation and data recovery procedure where applicable? [Y] N NS NA

Other Inspector Comments: The 2nd engineer demonstrated his familiarization of the Oily Water Separator (OWS) operation and 15ppm bilge alarm test at the time of the inspection. The OWS was calibration serviced by service technicians on 1 January 2023.

6.19 If the oily water separator is not fitted with an automatic stopping device, do entries in the Oil Record Book Part 1 indicate that it has not been used in a Special Area? Y N NS [NA]

Ballast Water Management

6.21 If the vessel is provided with an approved Ballast Water Treatment System, is the system in good order, used where required and are officer's familiar with the safe operation of the same? [Y] N NS NA

Other Inspector Comments: Vessel was loading harbour water into the ballast tanks through the approved ballast water treatment system during the inspection.

© Copyright OCIMF 2024

Additional Comments

6.99 Additional Comments

© Copyright OCIMF 2024

Chapter 7: Maritime Security

Policies and Procedures

7.5 Has the ship's security officer been trained to undertake this role and do they understand their responsibilities? Y N NS NA

Other Inspector Comments: Master was certified and assigned as ship's security officer.

7.12 Is an adequate deck watch being maintained to prevent unauthorised access in port? Y N NS NA

Other Inspector Comments: Gangway watch was continuously maintained. Inspector's identification was checked by the watchman prior to being escorted into the accommodation by the ship's officer. Vessel was provided with a closed-circuit television monitoring system covering the exposed decks, engine room compartment, etc.

7.13 Has the company provided a list of security charts, publications and guidelines to the ship? Y N NS NA

Other Inspector Comments: Vessel had industry publications like BMP5 and maritime security charts (paper).

Cyber Security

7.15 Are the crew aware of the company policy on the control of physical access to all shipboard IT/OT systems? Y N NS NA

Other Inspector Comments: The chief officer was in charge of Cyber security. The exposed USB ports on desktop computers and bridge systems were physically blocked using USB blockers.

7.17 Is Cyber Security awareness actively promoted by the company and onboard? Y N NS NA

Other Inspector Comments: Computer based training (including Cyber Security) was provided on board for all crew members.

Additional Comments

7.99 Additional Comments

© Copyright OCIMF 2024

Chapter 8: Cargo and Ballast Systems - Petroleum

Policies, Procedures and Documentation

8.3 Are cargo pump performance curves available, are deck officers aware of the test requirements for the cargo lines, vapour lines and inert gas lines in good order and is there recorded evidence of regular testing where applicable?

Y N NS NA

Other Inspector Comments: Records were available for pre-arrival discharge port integrity check of the cargo transfer system and tank cleaning lines. The cargo lines and tank cleaning lines on deck were hydrostatically tested to 14 bars (100% of their rated working pressure) at manifold on 28 September 2023.

Stability and Cargo Loading Limitations

8.4 If a loading computer or programme is in use, is it class approved, regularly tested and are officers aware of the test requirements including damage stability?

Y N NS NA

Other Inspector Comments: Class approved loading computer (IACS Type 3) was online to the closed gauging system of the cargo, ballast and fuel oil tanks and it was incorporated with damage stability calculations. Sighted records indicated that testing of loading computer's accuracy by built-in conditions and following comparison of results with Class approved test conditions carried out quarterly.

8.5 Has a cargo plan been prepared and followed with a detailed sequence of cargo and ballast transfers documented, stress, intact and damage stability and are any limitations, where applicable understood by the cargo watch officers and clearly documented?

Y N NS NA

Other Inspector Comments: Cargo discharge plan was pre-calculated for various stages of unloading conditions. Random checks during the inspection confirmed officer in charge of cargo operation was following the planned sequence and verifying results on an hourly basis.

Cargo Operations and Related Safety Management

8.8 Are the cargo, ballast and stripping pumps, eductors and their associated instrumentation and controls including temperature monitoring, in good order and is there recorded evidence of regular testing?

Y N NS NA

Other Inspector Comments: No.2 & No.3 cargo pumps and No.1 ballast pump were seen in operation and found free from operational defects. Cargo and ballast pumps bearing, casing & stuffing box high temperature repeaters were fitted in CCR and were seen in operation without any abnormality. No.1 cargo pump and No.2 ballast pump were reported operational and used during previous cargo operations.

8.9 Are officers aware of the column/cofferdam purging routines where deep well pumps are fitted and is the pump leakage within tolerable limits?

Y N NS NA

© Copyright OCIMF 2024

Other Inspector Comments: A deep well submersible pump was not fitted.

8.11	Are the cargo and ballast system valves in good order and is there recorded evidence of regular testing? Other Inspector Comments: Hydraulically operated cargo and ballast system valves were to be tested annually. Last timing check was completed on 4 February 2024. Manufacturer's data was available for optimum opening and closing times.	Y	N	NS	NA
8.12	Are the cargo system ullage gauges, vapour locks and UTI tapes in good order and is there recorded evidence of regular testing? Other Inspector Comments: All cargo tanks were fitted with a remote level gauging system that provided ullage / temperature / pressure readouts in the CCR. The level gauging system's accuracy had been regularly checked by comparing it with a portable electronic gauging tape during cargo operations. A record of comparison was maintained. Additionally, the vessel had 4 UTI tapes with valid calibration certificates.	Y	N	NS	NA
8.14	Are the cargo tank high level and overfill alarms in good order and is there recorded evidence of regular testing? Other Inspector Comments: High level and independent overfill alarms were fitted to each cargo tank and were checked before each cargo operation as per records sighted. Both alarm systems were switched on for this discharge. The overfill alarm sensor of No.5 (S) cargo tank was tried out and found operational at the time of the inspection.	Y	N	NS	NA
8.15	Where fitted, is the condition of the cargo tank heating system satisfactory, is it regularly tested and is any observation tank free of oil? Other Inspector Comments: Both slop tanks (P&S) were installed with in-tank heating coils, which were not in use at the time of the inspection. Individual steam inlet valves were found isolated by blanks.	Y	N	NS	NA

© Copyright OCIMF 2024

Venting Arrangements

8.19 Are the officers aware of the primary and secondary cargo tank venting systems and are the systems functioning correctly?

Y | N | NS | NA

Other Inspector Comments: Vessel was handling two parcels of crude oil and cargo tanks' venting system during discharge was:
- Primary venting: Each cargo tank was fitted with a full flow pressure/vacuum (P/V) relief valve (+1400/-350 mmWG).
- Secondary venting: A liquid-filled P/V breaker (+1800/-700 mmWG).
Additionally, all cargo tanks were equipped with a remote pressure sensor that was set to alarm at: High: +154 mbar; Pre-high: +150 mbar; Pre-low: +15 mbar; Low: +5 mbar.

© Copyright OCIMF 2024

Inert Gas System

8.22	Was the inert gas system in use and operating satisfactorily at the time of the inspection? Other Inspector Comments: No.5 centre and No.5 (S) cargo tanks were checked for oxygen contents in a closed mode, and the resultant oxygen readings were less than 5%.	[Y]	N	NS	NA
8.23	Is there evidence to show that regular maintenance has been conducted on the inert gas system, including the overhaul of the non-return valve(s)? Other Inspector Comments: Records on the PMS showed that the non-return valve was thoroughly overhauled in October 2023 as part of bi-annual safety routines.	[Y]	N	NS	NA
8.26	Was the fixed oxygen analyser calibrated immediately prior to use of the inert gas system and do local and remote oxygen and pressure recorders, where fitted, agree? Other Inspector Comments: The inert gas generation system had a complete spare oxygen analyser. Sighted record indicated that both analysers were calibrated immediately prior to this discharge.	[Y]	N	NS	NA
8.29	If the vessel is provided with a nitrogen generator / bottle manifold system, are the officers and crew aware of the specific hazards associated with nitrogen gas?	Y	N	NS	[NA]
8.30	Are officers and ratings aware of safe entry requirements for the inert gas room(s), are these procedures being followed and where applicable, is fixed oxygen detection provided? Other Inspector Comments: Inert gas was being produced through the flue gas and fans were situated on inert gas platform, which was part of the engine room compartment. The vessel was constructed on 31 December 2015, and the inert gas generation space was not fitted with oxygen sensors or alarms.	Y	N	NS	[NA]
8.31	Are the officers' familiar with the dangers associated with over pressurisation of the cargo tanks and are procedures implemented to avoid over pressure due to purging, blowing and pigging with nitrogen? Other Inspector Comments: Vessel didn't use shore-supplied nitrogen.	Y	N	NS	[NA]

© Copyright OCIMF 2024

Crude Oil Washing

8.34 If the vessel is Crude Oil Washing, has the COW system been tested for integrity, appropriate checks complete and all associated COW equipment in good operational order? [Y] N NS NA

Other Inspector Comments: One of two grades of crude oil was being discharged at this terminal, and a total of four cargo tanks were planned to be crude oil washed before departure. Vessel was at bulk discharge stages. Only COW plan and pre-arrival checklist were sighted as the COW stage was not yet reached.

Manifold Arrangements

8.41 Are the manifolds and associated valves in good order, blank flanges of an equivalent rating to that of the pipelines and pressure gauges fitted outboard of the manifold valves on both sides and monitored for leakage? [Y] N NS NA

Other Inspector Comments: A device was fitted in CCR capable of monitoring and recording the load and discharge manifold pressure outboard of each port and starboard manifold valve.

Pump Rooms

8.45 Are bulkhead seals gas tight and, if required, well lubricated? [Y] N NS NA

Other Inspector Comments: Each cargo pump was fitted with an Auto Unloading System (AUS). The AUS and cargo pump bulkhead seal oil reservoirs were sufficiently filled.

8.46 Is the pump room gas monitoring system in good order, regularly checked and are officers aware of the alarm settings? [Y] N NS NA

Other Inspector Comments: The fixed P/R gas detection system was measuring the oxygen (O2), hydrocarbon (HC) and hydrogen sulphide (H2S) vapour concentration and was set to alarm at: O2 (19.5%); HC (10.0% LEL); H2S (2.5 ppm).

Cargo Hoses

8.49 If the vessel uses its own cargo hoses, are they in good order, pressure tested annually and is a record of all hose tests and inspections maintained on board? Y N NS [NA]

© Copyright OCIMF 2024

Ship to Ship Transfer Operations

8.52 Does the POAC have the necessary qualifications and experience and are officers aware of these requirements? Y N NS [NA]

Other Inspector Comments: Vessel was not engaged in STS operation at the time of the inspection.

8.54 Are officers aware of the requirements of the ship-to-ship transfer checklists and are there records of STS operations maintained? [Y] N NS NA

Other Inspector Comments: Last STS operations were carried out in November 2023 and STS checklists were sighted.

8.55 If a ship-to-ship transfer was in progress during the inspection, was it conducted in accordance with the recommendations of the OCIMF/ICS STS Transfer Guide? Y N NS [NA]

Additional Comments

8.199 Additional Comments

Vibration monitoring repeaters for the cargo and ballast pumps and pump room ventilation fans were provided in the CCR.

Chapter 9: Mooring

Mooring Equipment Documentation and Management

9.4 Have the operator's policies on line inspections, retirement and wear zone management been implemented as outlined in the Line Management Plan? [Y] N NS NA

Other Inspector Comments: A maximum lifespan of 10 years has been established for mooring wire ropes, with a turnover end-to-end requirement of 5 years.

© Copyright OCIMF 2024

Mooring procedures

9.8	Are moorings satisfactorily deployed and tended? Other Inspector Comments: Mooring pattern deployed was 4 (head/stern lines) x 4 (breast lines fore and aft) x 2 (spring lines forward and aft) at the time of the inspection.	[Y]	N	NS	NA
9.9	Are mooring lines secured to bitts and turned up correctly?	Y	N	NS	[NA]
9.12	If mooring tails are fitted to wires or HMSF lines, do they have proper connections and are they correctly fitted? Other Inspector Comments: Synthetic mooring tails (TDBF 165T) were connected to steel wire ropes (MBL 115T) using joining shackles (MBL 180T). A risk assessment for using higher strength mooring tails was available for review.	[Y]	N	NS	NA

Mooring equipment

9.16	If mooring winches in a gas hazardous area are electrically powered, are motors Ex 'd' rated and have insulation tests been carried out and the results recorded.	Y	N	NS	[NA]

Anchoring equipment

9.24	Is the crew aware of the design limitations of their anchor windlass and systems? Other Inspector Comments: The chief officer was interviewed and appeared to be familiar with company procedures for anchoring operations.	[Y]	N	NS	NA

© Copyright OCIMF 2024

Single Point Moorings

9.26	If the vessel is equipped for mooring at single point moorings, does it meet the recommendations as applicable, contained in Mooring Equipment Guidelines? Other Inspector Comments: Each side SPM pick-up hawser could be directly led to a winch storage drum without the assistance of a roller.	[Y]	N	NS	NA
9.27	If the vessel is fitted with a hydraulically operated bow stopper, are safeguards provided to prevent its accidental release?	Y	N	NS	[NA]

Additional Comments

9.99	Additional Comments

Chapter 10: Engine and Steering Compartments

© Copyright OCIMF 2024

Policies, Procedures and Documentation

10.2 If the machinery space is certified for unmanned operation is it being safely operated in that mode without regular alarms occurring under normal conditions? [Y] N NS NA

Other Inspector Comments: Machinery space of this vessel was certified for unmanned operation and it was operated in UMS mode when the ship was at sea. During this inspection, the vessel was manned for cargo operation.

10.7 Does the operator subscribe to a fuel, lube and hydraulic oil testing programme on a frequency in accordance with the manufacturers recommendations and are there procedures to act on these results? [Y] N NS NA

Other Inspector Comments: Vessel was subscribed to a fuel and lube oil testing program. Bunker samples of high sulphur fuel oil (HSFO) and low sulphur marine gas oil (LSMGO) were sent to VPS for testing after each bunkering operation. Lube and hydraulic oil samples were tested at accredited laboratories as below:
(1) Every 3 months (+/- 1 month): Main engine (M/E), M/E cylinder scavenge drains, auxiliary engines (A/Es) and stern tube. Samples were tested in November 2023 or December 2023 and were normal, except that the samples from #2-#6 M/E cylinder drain oils were reported to be in "Alert" condition but fit for further use due to the presence of higher Sodium or Phosphorus.
(2) Every 6 months: Steering gears and winch/windlass hydraulic power packs. Analysis reports dated 21 September 2023 announced that all samples were normal.
(3) Every 12 months: Remote control valves, hose handling cranes, provision cranes and cargo pump turbines. All samples were tested in November 2023 or December 2023 and were normal.

As reported by the chief engineer, samples of the #1 group would be landed ashore for testing upon arrival at Singapore till the middle of March 2024.

10.10 Are the engineers aware of the requirements and precautions necessary to control the change from residual to low-sulphur fuels and are these requirements posted? [Y] N NS NA

Other Inspector Comments: The chief engineer well explained the fuel oil changeover requirements and procedures while interview. A record of fuel oil changes was reviewed and found satisfactory.

10.11 If the vessel is fitted with a class approved Exhaust Gas Cleaning System are the officers well familiar with the system and safety requirements and are these documented? [Y] N NS NA

Other Inspector Comments: Vessel was retrofitted with an open-loop Exhaust Gas Cleaning System that was able to remove Sulphur oxides from exhaust gases of the M/E and A/Es. Engineers interviewed appeared to be familiar with the system and safety requirements.

© Copyright OCIMF 2024

Planned Maintenance

10.12 Are the officers' familiar with the planned maintenance system and is the system being followed and maintained up to date? [Y] N NS NA

Other Inspector Comments: The computerised planned maintenance and spare parts inventory control programme was in place and was up to date. No overdue job was apparent on the PMS at the time of the inspection.

Safety Management

10.16 Are engineers aware of the testing requirements and able to demonstrate familiarity with the procedure for testing of emergency equipment? [Y] N NS NA

Other Inspector Comments: The emergency equipment testing procedures/instructions were posted on site and the 2nd engineer explained the test intervals. Following equipment was tried out during this inspection: Topping up air compressor, emergency generator, emergency steering and engineers' call alarms.

© Copyright OCIMF 2024

Fire Fighting Equipment

10.19	Are diesel engine fuel delivery pipes adequately jacketed or screened, exhaust lines and hot surfaces protected from spray and surrounding areas free from fuel or lube oil leakage? Other Inspector Comments: Fuel oil leakage alarms of the M/E and No.1 A/E were tested and found operational.	[Y]	N	NS	NA
10.21	If the vessel class notation allows UMS operation, are main engine bearing temperature monitors, or the crankcase oil mist detector, in good order? Other Inspector Comments: Oil mist detectors were fitted in the M/E crankcase - system alarm was tested and found satisfactory.	[Y]	N	NS	NA
10.22	Where hydraulic aggregate pumps are located within the main engine compartment, is an oil mist detector fitted?	Y	N	NS	[NA]
10.23	Are the main switchboard, alternators and other electrical equipment satisfactorily protected from water spray? Other Inspector Comments: The main switchboard was housed inside the engine control room.	[Y]	N	NS	NA
10.30	Is the bilge high level alarm system regularly tested and are records maintained? Other Inspector Comments: Engine room forward bilge high level alarms (P&S) were tested and found operational during this inspection.	[Y]	N	NS	NA

© Copyright OCIMF 2024

Machinery Status

10.32	Are the following, where applicable, all in good order and do they appear to be well maintained? Other Inspector Comments: No.2 & No.3 A/Es and two auxiliary oil-fired boilers were in operation at the time of the inspection, and both boilers were being operated in automatic mode. The plants and associated fittings were clean and free from apparent leakages.	[Y]	N	NS	NA
10.34	Are officers fully familiar with all starting procedures for the emergency generator and are these procedures clearly and displayed? Other Inspector Comments: The electrician started the emergency generator using both starting systems (battery & hydraulic) and it ran successfully. The remote fuel shut-off valve was also tried out and found in order.	[Y]	N	NS	NA
10.36	Where an emergency generator is not fitted, are engine room emergency batteries in good order and fully charged?	Y	N	NS	[NA]
10.38	Are switchboards free of significant earth faults? Other Inspector Comments: The 220 & 440 volts earth fault alarms were tested during the inspection round. Insulation test records were available.	[Y]	N	NS	NA

Steering Compartment

10.39	Are the officers aware of the test requirements for the steering gear both pre-departure and for emergency steering drills and have these tests been conducted satisfactorily with operating instructions clearly posted? Other Inspector Comments: The 2nd engineer satisfactorily demonstrated the operation of the emergency steering gear in the presence of the inspector. Ship's heading and communication with the bridge were also verified. Last emergency steering drill was carried out on 17 February 2024.	[Y]	N	NS	NA
10.44	Are the officers and crew aware of the safe operating requirements of any watertight doors fitted? Other Inspector Comments: A sliding watertight door was not fitted.	Y	N	NS	[NA]

© Copyright OCIMF 2024

Additional Comments

10.99 Additional Comments

Chapter 11: General Appearance and Condition

Electrical Equipment

11.9 Are the deck lights all operational and sufficient in number and range to illuminate the deck to facilitate safe working during darkness? [Y] N NS NA

Other Inspector Comments: During deck walks, the deck working lights, out passage lights and emergency lights were switched on and found in order.

Accomodation Areas

11.17 Are personnel alarms in refrigerated spaces in good order and operational? [Y] N NS NA

Other Inspector Comments: Refrigerated space personnel alarms and door opening devices were checked by the cook and found satisfactory.

Additional Comments

11.99 Additional Comments

Visible area of the port side hull was clean and free from any significant dents or marine growth and was observed in good condition. The coating remained largely intact with some coating damages to the finish coating and fender skid marks at isolated places. Upper decks, main deck and accommodation external were well painted and maintained and were free of hard rust. A high level of cleanliness and hygiene was observed in alleyways, public spaces, sanitary areas, stores and food handling spaces.

Operator's initial comments entered by: Captain Antonios Georgiou [operations@marantankers.gr]

Operator's subsequent comments entered by: Captain Antonios Georgiou [operations@marantankers.gr]

Operator's Initial General Comments

Operator's Subsequent General Comments

© Copyright OCIMF 2024

Entered by: Captain Antonios Georgiou [operations@marantankers.gr]
Date: 05 Mar 2024 15:05:10

VIQ 1.14 Is an up to date OCIMF Harmonised Vessel Particulars Questionnaire (HVPQ) maintained and is it readily available?
HVPQ 1.1.13.3, The specific amount of P&I cover cannot be changed due to software's restriction. The correct coverage is mentioned in the previous entry.
HVPQ 1.2.3.4, has been corrected and published accordingly.
HVPQ 2.1.5 DNV attended for verification survey on the 2nd of March and Safety Construction certificate short term was issued with expiration date 18/03/2024.
HVPQ 5.3.8.1 Rescue boat located portside HVPQ has been updated accordingly.
HVPQ 6.1.13.2 pressure test of cargo piping was conducted on 17.5 bar and was correctly recorded on HVPQ.
HVPQ 6.1.14.2, has been corrected and published accordingly.
HVPQ 9.7.3, has been corrected and published accordingly.
HVPQ 9.16.5, has been corrected and published accordingly.
HVPQ 10.1.7, has been corrected and published accordingly.

© Copyright OCIMF 2024