Detailed Diagnostic Report (DDR)

1. Property Issue Summary

Overview: The property has several issues including dampness, hollowness, and thermal bridging. The critical issues include leakage, plumbing issues, and cracks in the external wall. Moderate issues include mild dampness, gaps between tile joints, and thermal issues.

Critical Issues: Leakage, Plumbing issues, Cracks in the external wall

Moderate Issues: Mild dampness, Gaps between tile joints, Thermal issues

2. Area-wise Observations

Hall

Issues: Dampness, Hollowness

Description: Observed dampness at the skirting level and hollowness in the skirting levels.

Thermal Findings: Thermal bridging issue indicated by a temperature reading of 32.5°C.

Bedroom

Issues: Dampness, Hollowness

Description: Observed dampness at the skirting level and hollowness in the skirting

levels.

Thermal Findings: Thermal issues indicated by hollowness.

Bathroom

Issues: Dampness, Hollowness, Thermal issues

Description: Observed dampness, hollowness, and thermal issues in the Common Bathroom tile.

Thermal Findings: Temperature anomaly of 25°C (77°F) near a suspected water leak or condensation issue.

Parking Area

Issues: Seepage, Hollowness, Plumbing issue, Outlet Leakage

Description: Observed seepage, hollowness, plumbing issue, and outlet leakage in the Parking Area.

Thermal Findings: Not Available

3. Probable Root Causes

Leakage: Concealed plumbing issues

Plumbing issues: Damage in Nahani trap/Brickbat coba under

Cracks in the external wall: Not Available

4. Severity Assessment

Area	Issue	Severity	Urgency	Reasoning
Hall	Dampness	Medium	Short term	Dampness can lead to further damage if not addressed.
Bedroom	Dampness	Medium	Short term	Dampness can lead to further damage if not addressed.
Bathroom	Thermal issues	High	Immediate	Thermal issues can lead to structural damage if not addressed.
Parking Area	Leakage	High	Immediate	Leakage can lead to structural damage if not addressed.

5. Recommended Actions

Hall: Address dampness and hollowness issues

Bedroom: Address dampness and hollowness issues

Bathroom: Address thermal issues and leakage

Parking Area: Address leakage and plumbing issues

6. Additional Notes

Not Available

7. Missing or Unclear Information

Not Available

Generated by AI DDR System based on actual inspection documents.
This report is for informational purposes and should be verified by a qualified professional.