

Detailed Diagnostic Report

Property Issue Summary

Thermal inspection identified abnormal temperature rises in electrical components.

Area-wise Observations

Boiler Room:

High temperature detected in contactor connections.

Probable Root Cause

Loose or deteriorated electrical connection.

Severity Assessment

High severity due to excessive temperature rise.

Recommended Actions

Inspect and tighten electrical connections.

Additional Notes

Inspection conducted using thermal imaging equipment.

Missing or Unclear Information

Load history Not Available

Area Evidence Images

![image_20_1.jpeg](extracted_content/images/thermal/image_20_1.jpeg)

![image_54_2.jpeg](extracted_content/images/thermal/image_54_2.jpeg)

![image_18_0.jpeg](extracted_content/images/thermal/image_18_0.jpeg)

![image_32_1.jpeg](extracted_content/images/thermal/image_32_1.jpeg)

![image_46_2.jpeg](extracted_content/images/thermal/image_46_2.jpeg)

![image_20_0.png](extracted_content/images/inspection/image_20_0.png)

![image_20_1.png](extracted_content/images/inspection/image_20_1.png)

![image_20_3.png](extracted_content/images/inspection/image_20_3.png)

![image_20_2.png](extracted_content/images/inspection/image_20_2.png)

![image_0_1.png](extracted_content/images/inspection/image_0_1.png)