Q. Consider a process with the following transfer functions:

$$y(s) = \frac{2}{(3s+1)(5s+1)}F(s) + \frac{1}{4s+1}T(s)$$


$$F(s) = \frac{3}{2s+1}u(s) + \frac{1}{s+1}P(s)$$

- a) Draw a feedback control block diagram for controlling y by manipulating u and tune a PI controller using Ziegler-Nichols (Z-N) tuning correlations $(K_c = \frac{K_u}{2.2}; \tau_I = \frac{P_u}{1.2})$.
- b) Since P changes frequently, the above feedback control strategy is not efficient and a cascade control strategy has to be tried.
 - a. Draw a cascade control block diagram
 - Design the slave controller using direct synthesis approach (reference/desired time constant is 20% of the process time constant)
 - c. Design the master controller using Z-N tuning technique
- C) The cascade control strategy can not handle the large and frequent changes in T and therefore to be augmented with a feedforward control strategy. T variable is measured and the sensor transfer function is unity. Draw the augmented control block diagram which should include cascade and feedforward control strategy. Find the feedforward controller equation (FFC).
- d) Is FFC designed above physically realizable? If no, make it physically realizable by converting First order with dead time (FOTD) model.

[0.5+2+0.5+1+2+1+1+2]

Solution

Feedback Control Block diagram



To find the PI controller parameter using Z-N method, we take $G_c=K$ and write the characteristic equation as below.

$$1 + K \cdot \frac{6}{(2s+1)(3s+1)(5s+1)} = 0 \qquad \text{Or, } 30s^3 + 31s^2 + 10s + 1 + 6K = 0$$

Put
$$s = j\omega$$
, $-30j\omega^3 - 31\omega^2 + 10j\omega + 1 + 6K = 0$

$$(-31\omega^2 + 1 + 6K) + i(-30\omega^3 + 10\omega) = 0 + i.0$$


Or,
$$-30\omega^3 + 10\omega = 0$$
 or, $\omega = 0$, or $\omega = \pm \frac{1}{\sqrt{3}}$

for $\omega=0$, $K=-\frac{1}{6}$ which is not feasible because process gain is positive

for
$$\omega = \frac{1}{\sqrt{2}}$$
, $K = K_u = \frac{14}{9} = 1.55$ and $P_u = 2 \pi \sqrt{3} = 10.88$

for
$$\omega=\frac{1}{\sqrt{3}}$$
, $K=K_u=\frac{14}{9}=1.55$ and $P_u=2~\pi~\sqrt{3}=10.88$
So PI controller parameters are: $K_c=\frac{1.55}{2.2}=0.704$ and $\tau_I=\frac{10.88}{1.2}=9.06$

(b) Cascade control block diagram Master controller is C1 and slave controller is C2



Slave controller C2 using DSA:
$$\tau_r = 0.2 * 2 = 0.4$$
 and $C2(s) = \frac{1}{\tau_r s} \frac{1}{g_p} = \frac{1}{0.4 \text{ s}} \cdot \frac{2s+1}{3} = \frac{2}{1.2} \left(1 + \frac{1}{2s}\right)$

Master Controller C1 using Z-N:

Characteristic equation :
$$1 + K \cdot \frac{1}{0.4 \, s + 1} \cdot \frac{2}{(3s+1)(5s+1)} = 0$$
 or, $6s^3 + 18.2s^2 + 8.4s + 1 + 2K = 0$

Put
$$s = j\omega$$
, $-6j\omega^3 - 18.2\omega^2 + 8.4j\omega + 1 + 2K = 0$


Or,
$$(-18.2\omega^2 + 1 + 2K) + j(-6\omega^3 + 8.4\omega) = 0 + j.0$$

Or,
$$-6\omega^3 + 8.4\omega = 0$$
 this gives $\omega = 0$ or $\omega = \pm \sqrt{1.4}$

Or,
$$K = K_u = 12.24$$
 and $P_u = \frac{2\pi}{\sqrt{1.4}} = 5.31$

So, PI controller parameter $K_c = 5.56$ and $\tau_I = 4.42$

(c) Feedforward-cascade control block diagram



$$y(s) = \frac{c1(s)gs(s)g_1(s)}{1 + c1(s)gs(s)g_1(s)} ysp(s) + \frac{FFC(s)g_1(s)gs(s) + g_{d1}(s)}{1 + c1(s)gs(s)g_1(s)} T(s) + \frac{g_1(s)g_{d2}(s)}{1 + c1(s)gs(s)g_1(s)} P(s)$$

Where,
$$g_1(s) = \frac{2}{(3s+1)(5s+1)} g_2(s) = \frac{C2(s)g_2(s)}{1+C2(s)g_2(s)} g_2(s) = \frac{3}{2s+1} g_{d1}(s) = \frac{1}{4s+1} g_{d2}(s) = \frac{1}{s+1}$$
 And C1 and C2 is designed in (b).

To design the FFC, y should be zero for any changes in T i.e. $FFC(s)g_1(s)gs(s) + g_{d1}(s) = 0$

$$FFC(s) = -\frac{g_{d1}(s)}{g_1(s)gs(s)} = -0.5 \frac{(3s+1)(5s+1)(0.4s+1)}{4s+1}$$

(d) the FFC designed is not physically realizable.

$$g_1(s)gs(s) = g_p(s) = \frac{2}{(0.4s+1)(3s+1)(5s+1)} = \frac{A}{0.4s+1} + \frac{B}{3s+1} + \frac{C}{5s+1}$$

$$A|_{s=-\frac{1}{0.4}} = 0.0268 \ B|_{s=-\frac{1}{3}} = -3.4615 \ C|_{s=-\frac{1}{5}} = 5.4348$$

$$\begin{split} g_p'(s) &= -\frac{0.4A}{(0.4s+1)^2} - \frac{3B}{(3s+1)^2} - \frac{5C}{(5s+1)^2} & \text{or, } g_p'(0) = -0.4A - 3B - 5C = -16.8 \\ g_p''(s) &= \frac{0.32A}{(0.4s+1)^3} + \frac{18B}{(3s+1)^3} + \frac{50C}{(5s+1)^3} & \text{or, } g_p''(0) = 0.32A + 18B + 50C = 209.44 \end{split}$$

$$(\tau + \theta) = -\frac{g_p'(0)}{g_p(0)} = \frac{16.8}{2} = 8.4$$
 and $\tau^2 = \frac{g_p''(0)}{g_p(0)} - (\tau + \theta)^2 = \frac{209.44}{2} - 8.4^2 = 34.16$

So,
$$\tau = 5.8447$$
 and $\theta = 2.5553$ therefore, $g_p(s) \approx \frac{2e^{-2.5553s}}{5.8447s + 1}$

And
$$FFC(s) = -\frac{g_{d1}(s)}{g_p(s)} = -0.5 \frac{5.8447s+1}{4s+1} e^{2.5553s} \approx -0.5 \frac{8.4s+1}{4s+1}$$

Simplest way to make it physically realizable is to neglect 0.4s+1 as 0.4 << 5 and add the two time constants i.e,

$$FFC(s) = -0.5 \frac{8s+1}{4s+1}$$