




07/21/2025

REDUCTION IN TURN AROUND TIME

Identified Bottlenecks for improvement

PRESENTED BY:


Swati Kumari




TAT Overall process

01/09


Breakdown of Turn Around Time



As In Process




Proposed





This can remove 4 steps involving security and removing possible human error

Gate Entry



Suggestion to Club Steps involved in Entry



Document can have QR to be scanned. This can reduce steps involved Document Verification /Issue of Entry Slip, Stamping, Sap Entry. At Gate NO. 02

Automated Sap Entry, verification of required information. After this it can generate DOCKET/SRR. Signed by authority. At Gate NO. 02

01 No Quality Inspection Before 11:30 Am

- Vendors Wait until the inspection is done.
- Only 1 skilled person present, which is involved in documents and other activity.

02 Lack of Manpower

- Quality has 2 employee, for after 2 PM shift . But mostly one of workers is on vendor end. Causing increased workload on remaining person

03 Rush after 6 PM

- Mostly because Vendors deliver material at evening as they receive planing same day

04 Order of Prefrence

- Following FIFO always , seems ideal but ineffecient use of limited time.
- Critical is inspected first, but we wait until someone from shop comes and confirms it.


04/09

Quality Inspection

Finding different reasons of high rush of vendors , causing holding of truck and incresed TAT.

Solution

- 1 person must be present in 9:00 AM-2:00 PM shift dedicated only for Quality inspection.
- 2 person must be present in 2:00 PM -6:00 PM shift for dedicated only for Quality inspection.
- 3 person or more Should be present after 6:00 PM for quality inspection.




Alternative

Club different types of category for inspection

MaxTime + Less Time = A +F , B+E , C+D

- Now Distribute these Categories to Different counters
- this can bring Overall, balance between two available counters and Average time for inspection will also be reduced



Store

unloading of materials

Not Enough Trolleys present to unload Material like: Frame, Fork. At present 7 Trolleys are in CKD

Blocked CKD Gangway resulting in not enough space for Material to unload and store. Before it gets moved To Finished Goods store.

Mistmatch in MPQ and BPR: SCM has already provided MPQ & MOQ to PPC, But still BPR is not being generated as per MOQ & MPQ leading to Issues at receipt store due to quantity mismatch which should be adjusted .

07/09



ALTERNATIVES

08/09

Introduce more Trolleys.

Materials delivered by the vendor at the designated location shall be handled and properly stored by the store personnel in the assigned storage area.

ASN (Advanced Shipping Notice) system is in process. It was temporarily discontinued due to the transition from internal planning to Vector Planning within the organization. However, we are currently working on restarting the ASN process to ensure accurate reflection of Ordered and Received Quantities as per schedule, similar to the earlier functionality

Conclusion

The study highlights key bottlenecks contributing to increased Turn Around Time (TAT), including delays in quality inspection, limited availability of trolleys, blocked gangways, and procedural delays in handling excess inventory.

Addressing these issues—by improving communication with PPC and Stores, streamlining quality checks, ensuring adequate material handling equipment, and optimizing space management—can significantly enhance operational efficiency. A coordinated effort between departments such as Quality, Store, PPC and Purchase is essential for sustainable TAT reduction..