

ELEC 207 Part B

Control Theory Lecture 9: Control System Design (1)

Prof Simon Maskell CHAD-G68 s.maskell@liverpool.ac.uk 0151 794 4573



Root Locus

Number of Branches

- A branch is the path that one pole traverses.

There are an many branches as there are closed-loop poles.

 $1 + KG(s) = 0 \qquad \qquad G(s) = \frac{Z_1s\rangle}{P(s)}$ P(s) + KZ(s) = 0

If a pole has an imaginary part, there will be a complex compagate pole. So, we know that the root locus is symmetric about the real axis.

Start and End Points

= 5e, if we vary K, the closed-loop poles will move from the open-loop poles (at K=0) to the open-loop zeros (at $K=\infty$). [4] [4]

$$\frac{Y(s)}{X(s)} = \frac{KG(s)}{1 + KG(s)}$$

Angles of Departure and Arrival

Imaginary Axis Crossings

- We know that poles in the RMF will cases instability. We can use the Routh-Hurwitz criteria to find K: We find a K that forces a row in the Routh-Hurwitz while to be zero.

Real-Axis Breakaway Points



ELEC 207 Part B

Control Theory Lecture 9: Control System Design (1)


Prof Simon Maskell
CHAD-G68
s.maskell@liverpool.ac.uk
0151 794 4573



This lecture covers:

• Root locus diagram representation for a closed loop system with variable gain.

ELEC 207B: Timeline



This lecture covers:

• Root locus diagram representation for a closed loop system with variable gain.

Root Locus

Number of Branches

- A branch is the path that one pole traverses.
- There are as many branches as there are closed-loop poles.

Symmetry

 If a pole has an imaginary part, there will be a complex conjugate pole. So, we know that the root locus is symmetric about the real axis.

Real-axis Segments

$$KG(s) = -1$$
 $\angle G(s) = -180 \pm k360$
 $G(s) = K_0 \frac{\prod_{i=1}^n (s - z_i)}{\prod_{j=1}^n (s - p_j)}$ $\angle (a \times b) = \angle a + \angle b$
 $\angle G(s) = \angle Z(s) = \angle P(s)$
 $= \sum_{i=1}^n \angle (s - p_i) = -180 \pm k360$

- For any point on the real axis, the contribution from any complex
- conjugate poles (or zeros) will cancel each other out.

 For two values of s on the real axis and either side of a zero or a pole.
- For two values of s on the real axis and either side of a zero or a pol then they will have values of ∠G(s) that differ by 180°.
- More precisely, the root locus exists at s on the real-axis to the left of an odd total number of real-axis open-loop poles and open-loop zeros.


Start and End Points

$$1 + KG(s) = 0$$

$$G(s) = \frac{Z(s)}{P(s)}$$

$$P(s) + KZ(s) = 0$$


 So, if we vary K, the closed-loop poles will move from the open-loop poles (at K=0)to the open-loop zeros (at K=∞).



$$\frac{Y(s)}{X(s)} = \frac{KG(s)}{1 + KG(s)}$$

Infinite Zeros

- If n<m then there are more poles than there are (finite) zeros.
 The poles move from the open-loop poles to the open-loop zeros, so we have to think what happens when |s|=∞.
- As |s|→00, the locus will asymptote to straight lines



Angles of Departure and Arrival

- Imagine a point on the root locus that is a tiny distance ε away from an open-loop pole. We know that the angles must add up to an odd multiple of 180°.
- We can solve for the angle between the point that is ϵ away and the open-loop pole. This enables us to find the angle of departure and arrival of complex poles and zeros.

Imaginary Axis Crossings


- We know that poles in the RHP will cause instability. We can use the Routh-Hurwitz criteria to find K:
- We find a K that forces a row in the Routh-Hurwitz table to be zero.
- The associated auxiliary equation can then be solved for s.

Real-Axis Breakaway Points

$$K = \frac{1}{|G(s)|}$$

 K is a local maximum or minimum when the root locus breaks away from the real axis. So, we can differentiate K wrt s, set to zero and solve for \u03c4.





$$\frac{Y(s)}{X(s)} = \frac{KG(s)}{1 + KG(s)}$$

Root Locus

Number of Branches

- A branch is the path that one pole traverses.
- There are as many branches as there are closed-loop poles.

Symmetry

 If a pole has an imaginary part, there will be a complex conjugate pole. So, we know that the root locus is symmetric about the real axis.

Real-axis Segments

$$KG(s) = -1$$
 $\angle G(s) = -180 \pm k360$
 $G(s) = K_0 \frac{\prod_{i=1}^n (s - z_i)}{\prod_{j=1}^n (s - p_j)}$ $\angle (a \times b) = \angle a + \angle b$
 $\angle G(s) = \angle Z(s) = \angle P(s)$
 $= \sum_{i=1}^n \angle (s - p_i) = -180 \pm k360$

- For any point on the real axis, the contribution from any complex
- conjugate poles (or zeros) will cancel each other out.

 For two values of s on the real axis and either side of a zero or a pole.
- For two values of s on the real axis and either side of a zero or a pol then they will have values of ∠G(s) that differ by 180°.
- More precisely, the root locus exists at s on the real-axis to the left of an odd total number of real-axis open-loop poles and open-loop zeros.


Start and End Points

$$1 + KG(s) = 0$$

$$G(s) = \frac{Z(s)}{P(s)}$$

$$P(s) + KZ(s) = 0$$


 So, if we vary K, the closed-loop poles will move from the open-loop poles (at K=0)to the open-loop zeros (at K=∞).



$$\frac{Y(s)}{X(s)} = \frac{KG(s)}{1 + KG(s)}$$

Infinite Zeros

- If n<m then there are more poles than there are (finite) zeros.
 The poles move from the open-loop poles to the open-loop zeros, so we have to think what happens when |s|=∞.
- As |s|→00, the locus will asymptote to straight lines



Angles of Departure and Arrival

- Imagine a point on the root locus that is a tiny distance ε away from an open-loop pole. We know that the angles must add up to an odd multiple of 180°.
- We can solve for the angle between the point that is ϵ away and the open-loop pole. This enables us to find the angle of departure and arrival of complex poles and zeros.

Imaginary Axis Crossings

- We know that poles in the RHP will cause instability. We can use the Routh-Hurwitz criteria to find K:
- We find a K that forces a row in the Routh-Hurwitz table to be zero.
- The associated auxiliary equation can then be solved for s.

Real-Axis Breakaway Points

$$K = \frac{1}{|G(s)|}$$

 K is a local maximum or minimum when the root locus breaks away from the real axis. So, we can differentiate K wrt s, set to zero and solve for \u03c4.



Start and End Points


$$1 + KG(s) = 0$$


$$G(s) = \frac{Z(s)}{P(s)}$$

$$P(s) + KZ(s) = 0$$

• So, if we vary K, the closed-loop poles will move from the open-loop poles (at K=0)to the open-loop zeros (at $K=\infty$).







Start and End Points

$$1 + KG(s) = 0$$

$$G(s) = \frac{Z(s)}{P(s)}$$

$$P(s) + KZ(s) = 0$$

• So, if we vary K, the closed-loop poles will move from the open-loop poles (at K=0)to the open-loop zeros (at $K=\infty$).





Number of Branches


- A branch is the path that one pole traverses.
- There are as many branches as there are closed-loop poles.

Symmetry

• If a pole has an imaginary part, there will be a complex conjugate pole. So, we know that the root locus is symmetric about the real axis.








Symmetry

• If a pole has an imaginary part, there will be a complex conjugate pole. So, we know that the root locus is symmetric about the real axis.



Real-axis Segments

$$KG(s) = -1 \angle G(s) = -180 \pm k360$$


$$G(s) = K_G \frac{\prod_{i=1}^{m} (s - z_i)}{\prod_{j=1}^{n} (s - p_j)} \angle (a \times b) = \angle a + \angle b$$


$$\angle G(s) = \angle Z(s) - \angle P(s)$$

$$= \sum_{i=1}^{m} \angle (s - z_i) - \sum_{i=1}^{n} \angle (s - p_i) = -180 \pm k360$$

- For any point on the real axis, the contribution from any complex conjugate poles (or zeros) will cancel each other out.
- For two values of s on the real axis and either side of a zero or a pole, then they will have values of $\angle G(s)$ that differ by 180°.
- More precisely, the root locus exists at s on the real-axis to the left of an odd total number of real-axis open-loop poles and open-loop zeros.







Real-axis Segments

$$KG(s) = -1 \angle G(s) = -180 \pm k360$$

$$G(s) = K_G \frac{\prod_{i=1}^{m} (s - z_i)}{\prod_{j=1}^{n} (s - p_j)} \angle (a \times b) = \angle a + \angle b$$

$$\angle G(s) = \angle Z(s) - \angle P(s)$$


$$= \sum_{i=1}^{m} \angle (s - z_i) - \sum_{i=1}^{n} \angle (s - p_i) = -180 \pm k360$$


- For any point on the real axis, the contribution from any complex conjugate poles (or zeros) will cancel each other out.
- For two values of s on the real axis and either side of a zero or a pole, then they will have values of $\angle G(s)$ that differ by 180°.
- More precisely, the root locus exists at s on the real-axis to the left of an odd total number of real-axis open-loop poles and open-loop zeros.



Infinite Zeros


- If n<m then there are more poles than there are (finite) zeros. The poles move from the open-loop poles to the open-loop zeros, so we have to think what happens when $|s|=\infty$.
- As $|s| \to \infty$, the locus will asymptote to straight lines





Infinite Zeros


- If n<m then there are more poles than there are (finite) zeros. The poles move from the open-loop poles to the open-loop zeros, so we have to think what happens when $|s|=\infty$.
- As $|s| \to \infty$, the locus will asymptote to straight lines




Real-Axis Breakaway Points

$$K = \frac{1}{|G(s)|}$$

• K is a local maximum or minimum when the root locus breaks away from the real axis. So, we can differentiate K wrt s, set to zero and solve for σ .





$$G(s) = \frac{1}{(s+3)(s+1)(s-1)}$$

$$\frac{d}{ds}(s+3)(s+1)(s-1) = \frac{d}{ds}(s^3+3s^2-s-3) = 3s^2+6s-1 = 0$$


$$s = \frac{-6 \pm \sqrt{6^2+4.3.1}}{2.3} = -1 \pm \frac{2}{\sqrt{3}}$$

$$Re(s)$$

$$G(s) = \frac{1}{(s+3)(s+1)(s-1)}$$

$$\frac{d}{ds}(s+3)(s+1)(s-1) = \frac{d}{ds}(s^3+3s^2-s-3) = 3s^2+6s-1 = 0$$


$$s = \frac{-6 \pm \sqrt{6^2 + 4.3.1}}{2.3} = -1 \pm \frac{2}{\sqrt{3}}$$




Real-Axis Breakaway Points

$$K = \frac{1}{|G(s)|}$$

• K is a local maximum or minimum when the root locus breaks away from the real axis. So, we can differentiate K wrt s, set to zero and solve for σ .






Imaginary Axis Crossings

- We know that poles in the RHP will cause instability. We can use the Routh-Hurwitz criteria to find K:
- We find a K that forces a row in the Routh-Hurwitz table to be zero.
- The associated auxiliary equation can then be solved for s.

$$s = \pm \sqrt{-8} = \pm 2\sqrt{2}j$$



EX

$$1 + \frac{K}{s^3 + 5s^2 + 8s + 6} = 0$$


$1 + \frac{K}{s^3 + 5s^2 + 8s + 6} = 0$	$(6+K) - 8 \times 5 = 0$
$\begin{array}{ c c c c c c }\hline s^3 & & 1 & & 8 \\ \hline s^2 & & 5 & & 6+K \\ \hline s^1 & -\frac{1}{5} & 1 & 8 & & 0 \\ \hline s^5 & 5 & 6+K & & 0 \\ \hline \end{array}$	$5s^2 + 6 + K = 0$ $5s^2 + 40 = 0$
s^0	$s = \pm \sqrt{-8} = \pm 2\sqrt{2}j$

$$(6+K) - 8 \times 5 = 0$$

$$5s^2 + 6 + K = 0$$

$$5s^2 + 40 = 0$$

$$s = \pm \sqrt{-8} = \pm 2\sqrt{2}j$$




Imaginary Axis Crossings

- We know that poles in the RHP will cause instability. We can use the Routh-Hurwitz criteria to find K:
- We find a K that forces a row in the Routh-Hurwitz table to be zero.
- The associated auxiliary equation can then be solved for s.

Angles of Departure and Arrival

- Imagine a point on the root locus that is a tiny distance ε away from an open-loop pole. We know that the angles must add up to an odd multiple of 180°.
- We can solve for the angle between the point that is ε away and the open-loop pole. This enables us to find the angle of departure and arrival of complex poles and zeros.



Angles of Departure and Arrival

- Imagine a point on the root locus that is a tiny distance ε away from an open-loop pole. We know that the angles must add up to an odd multiple of 180°.
- We can solve for the angle between the point that is ε away and the open-loop pole. This enables us to find the angle of departure and arrival of complex poles and zeros.

Root Locus

Number of Branches

- A branch is the path that one pole traverses.
- There are as many branches as there are closed-loop poles.

Symmetry

 If a pole has an imaginary part, there will be a complex conjugate pole. So, we know that the root locus is symmetric about the real axis.

Real-axis Segments

$$KG(s) = -1$$
 $\angle G(s) = -180 \pm k360$
 $G(s) = K_0 \frac{\prod_{i=1}^n (s - z_i)}{\prod_{j=1}^n (s - p_j)}$ $\angle (a \times b) = \angle a + \angle b$
 $\angle G(s) = \angle Z(s) = \angle P(s)$
 $= \sum_{i=1}^n \angle (s - p_i) = -180 \pm k360$

- For any point on the real axis, the contribution from any complex
- conjugate poles (or zeros) will cancel each other out.

 For two values of s on the real axis and either side of a zero or a pole.
- For two values of s on the real axis and either side of a zero or a pol then they will have values of ∠G(s) that differ by 180°.
- More precisely, the root locus exists at s on the real-axis to the left of an odd total number of real-axis open-loop poles and open-loop zeros.


Start and End Points

$$1 + KG(s) = 0$$

$$G(s) = \frac{Z(s)}{P(s)}$$

$$P(s) + KZ(s) = 0$$


 So, if we vary K, the closed-loop poles will move from the open-loop poles (at K=0)to the open-loop zeros (at K=∞).



$$\frac{Y(s)}{X(s)} = \frac{KG(s)}{1 + KG(s)}$$

Infinite Zeros

- If n<m then there are more poles than there are (finite) zeros.
 The poles move from the open-loop poles to the open-loop zeros, so we have to think what happens when |s|=∞.
- As |s|→00, the locus will asymptote to straight lines



Angles of Departure and Arrival

- Imagine a point on the root locus that is a tiny distance ε away from an open-loop pole. We know that the angles must add up to an odd multiple of 180°.
- We can solve for the angle between the point that is ϵ away and the open-loop pole. This enables us to find the angle of departure and arrival of complex poles and zeros.

Imaginary Axis Crossings

- We know that poles in the RHP will cause instability. We can use the Routh-Hurwitz criteria to find K:
- We find a K that forces a row in the Routh-Hurwitz table to be zero.
- The associated auxiliary equation can then be solved for s.

Real-Axis Breakaway Points

$$K = \frac{1}{|G(s)|}$$

 K is a local maximum or minimum when the root locus breaks away from the real axis. So, we can differentiate K wrt s, set to zero and solve for \u03c4.



This lecture covers:

• Root locus diagram representation for a closed loop system with variable gain.