## INDEX

	Subject	Chapter	Section Page
Н	H- and D-function (H, D Codes)	· 6 · · · · · 6 · · · ·	6.1.6 ····· 156 6.1.5 ···· 156 6.1.8 ···· 157
	High-Speed Cutting Feature (G100 through G102) · · · · · · · Hole Pattern Cycles (G70, G71, G72) † · · · · · · · · · · · · · · · · · ·	. 2	2. 9. 33 ···· 80 2. 9. 27 ··· 65
l	Inch/Metric Designation by G Code (G20, G21)† Input Format	. 2	2.1.1 ····· 1 2.1 ····· 1 8.6.3 ···· 185
	INSPECTION BEFORE TURNING ON POWER	. 4	4.7.1 ······140 4.3.8 ·····130
J	JOG FEEDRATE Switch	. 6	6. 1. 10 ····· 157 6. 1. 9 ····· 157
L	Label Skip Function	. 2	2.3.5 8
М	(M00, M01, M02, M30) M Codes for Stop	. 2	2.8.2 ···· 16 2.8.3 ···· 16 2.8.4 ··· 16
	(M97/M96) † Circular Path Mode On/Off on Tool Radius Compensation C	. 2	2.8.7 ···· 19 2.8.2 ···· 16 2.8.1 ··· 15 2.8.8 ··· 20
	M-FUNCTION LOCK Switch (Auxiliary Function Lock) MACHINE CONTROL STATION	. 6	8.6.4 ····· 186 ···· 178 6.1.24 ···· 160
	MANUAL OPERATION	. 7	7.7 ······175 6.1.7 ····156 6.1.15 ····159
	Maximum Programmable Dimensions	. 2	2.3.6 9 2.10.2 83 7.8175 7.9176 4.1.11117
	MIRROR IMAGE AXIS SELECTOR Switch  Mirror Image On/Off (M95/M94)  Miscellaneous Function (B-Function)†, 2Nd  MISCELLANEOUS FUNCTION (M-FUNCTION)  MODE SELECT Switches	. 2	. 6.1.25160 . 2.8.516 . 2.8.920 . 2.815 . 6.1.1155