


Analog signal from pressure sensor

Analog signal to arduino

V

Converts to digital value
So convert back-to analog



find volume by manually adding from vate over time

(delay in arduino and "integrate" overtime)