
plant step
of the study
0.1 % (specification)
Largest change of a metric (%)
10^{1}
10^{0}
10^{-1}
10^{-2}
10^{-3}
10^{-4}
10^{-5}
10^{-6}
62.5
125
250
500
1000
Plant step h (us), compared with h/2
no fault
loss of effectiveness 0.6, winch 3
break, cable 5
break, cable 5, stiff cable
break, cable 1
dashed: same run without sensor noise