Flight No	Aircraft Type	Date	Flight Route	Status	Delay Type	Duration (Hours)	Cost PKR(Million)	Delay Reason
PIA304	A320-200	1-1-22	KHI-LHE	Delayed	Bad Weather	4	0.5	Heavy Fog at destination
PIA783	B777-200ER	19-1-22	KHI-YYZ	Delayed	Technical	5	1.5	Unusual Engine noise during taxi
PIA123	B777-200ER	25-1-22	KHI-KUL	Delayed	Technical	7	4	Autopilot Malfunction
PIA210	A320-200	4-2-22	KHI-ISB	Delayed	Technical	3	0.9	Fluctuating N1/N2 reading
PIA612	A320-200	10-2-22	LHE-UET	Cancelled	Technical		4.9	Flap Asymmetry warning
PIA121	ATR42-500	23-2-22	PEW-CJL	Delayed	Bird Strike	2	0.5	Bird Strike
PIA465	A320-200	1-3-22	KHI-MUX	Delayed	Operational	2.5		Late Boarding
PIA910	B777-200ER	3-3-22	LHE-YYZ	Delayed	Technical	0	0.1	IFE System Failure
PIA422	B777-200ER	14-3-22	YYZ-LHE	Delayed	Operational	4	0	Fight Amongst Cabin Crew
PIA456	ATR42-500	5-4-22	KHI-GWD	Cancelled	Technical		2	Hydraulic Fluid Leak
PIA112	B777-200ER	11-4-22	ISB-YYZ	Delayed	Technical	3	0.5	GPS Signal Error
PIA312	A320-200	30-4-22	KHI-BAH	Delayed	Operational	2		Late Boarding
PIA302	A320-200	15-5-22	LHE-KHI	Delayed	Operational	2	0	Fuel Truck Delay/Miscommunication
PIA576	ATR42-500	27-5-22	SKZ-GWD	Delayed	Bird Strike	5	0.5	Bird Strike
PIA721	B777-200ER	18-6-22	LHE-SHJ	Delayed	Technical	2.5	0.15	Lavatory Flush System Failure
PIA789	A320-200	25-6-22	LHE-YYZ	Delayed	Technical	3	0.5	Air conditioning failure
PIA784	B777-200ER	5-7-22	YYZ-KHI	Delayed	Technical	5.5	2.5	Oxygen Msk Auto-deploy
PIA211	A320-200	15-7-22	ISB-KHI	Delayed	Bird Strike	1.5	0.07	Bird Strike
PIA279	A320-200	24-7-22	LHE-KWI	Delayed	Operational	2.5		Late Boarding
PIA622	A320-200	8-8-22	KHI-UET	Delayed	Operational	8	2	Brake Overheating after landing
PK301	B777-200ER	19-8-22	YYZ-ISB	Delayed	Technical	3	0.8	Leak In air duct
PIA121	ATR42-500	29-8-22	PEW-CJL	Delayed	Bird Strike	6	0.6	Bird Strike
PIA781	B777-200ER	4-9-22	ISB-YYZ	Delayed	Technical	2.5	1	Cargo Door Malfunction

PIA522	A320-200	10-9-22	LHE-ISB	Cancelled	Technical		2.5	Battery Overheating Incident
PIA800	A320-200	20-9-22	ISB-DXB	Delayed	Technical	4	5	Sudden APU Failure
PIA783	B777-200ER	1-10-22	KHI-YYZ	Delayed	Technical	2	0.4	Ground Power Unite Failure
PIA465	A320-200	30-10-22	KHI-MUX	Cancelled	Technical		4	Nose Gear Retraction Issue
PIA400	ATR42-500	19-11-22	SKZ-MUX	Delayed	Technical	6	1	Brake Failure
PIA729	B777-200ER	29-11-22	KHI-SHJ	Delayed	Technical	2	0.2	Ground Power Unite Failure
PIA826	A320-200	14-12-22	LHE-DXB	Delayed	Bad Weather	4	1	Bad Weather(too much wind)
PIA854	A320-200	19-12-22	KHI-DXB	Delayed	Technical	3	1.9	Engine Vibration Warning
PIA123	B777-200ER	10-1-23	KHI-KUL	Delayed	Operational	1.5		Late Boarding
PIA267	ATR42-500	21-1-23	ISB-KDU	Delayed	Bad Weather	5	1.9	Weather(snow) on runway
PIA934	ATR42-500	5-2-23	ISB-JED	Delayed	Operational	2	1	Late Boarding
PK300	B777-200ER	16-2-23	ISB-YYZ	Delayed	Technical	2	0.5	Air conditioning failure
PIA134	A320-200	2-3-23	KAHI-ISB	Delayed	Technical	1	0.05	Seatbelt light circuit failure
PIA888	A320-200	12-3-23	UET-KHI	Delayed	Technical	4	2.7	Main Door won't close
PIA722	B777-200ER	29-3-23	SHJ-LHE	Delayed	Technical	3.5	0.95	Brake Overheating after landing
PIA304	A320-200	8-4-23	KHI-LHE	Delayed	Technical	10	3	Hydraulic Fluid Leak
PIA-300	B777-200ER	20-4-23	ISB-YYZ	Delayed	Technical	1.5	0.25	GPS Signal Error
PIA540	ATR42-500	30-4-23	KHI-GWD	Delayed	Bird Strike	6	0.4	Bird nest in engine bay(True Incident)
PIA522	A320-200	19-5-23	LHE-ISB	Cancelled	External			Political Unrest in Lahore
PIA712	A320-200	19-5-23	LHE-JED	Cancelled	External			Political Unrest in Lahore
PIA612	A320-200	19-5-23	LHE-UET	Cancelled	External			Political Unrest in Lahore
PIA110	A320-200	19-5-23	LHE-PEW	Delayed	External	4		Political Unrest in Lahore
PIA309	A320-200	19-5-23	LHE-KHI	Delayed	External	3		Political Unrest in Lahore
PIA540	ATR42-500	20-5-23	KHI-GWD	Delayed	Technical	3	0.5	Leak In air duct
PIA640	A320-200	22-7-23	LHE-KWI	Delayed	Technical	2	1.5	Cargo Door Malfunction

PIA812	A320-200	30-7-23	KHI-UET	Cancelled	Technical		4.5	Radar Screen Blackout
PIA789	B777-200ER	20-8-23	LHE-YYZ	Delayed	Operational	2		Late Boarding
PIA125	B777-200ER	23-8-23	LHE-KUL	Delayed	Technical	18	7	Nose Gear Retraction Issue
PIA800	B777-200ER	7-9-23	ISB-DXB	Delayed	Technical	14	6	Cabin Pressurisation system failure
PIA540	B777-200ER	18-9-23	KHI-GWD	Delayed	Technical	2	0.5	Air conditioning failure
PIA783	B777-200ER	29-9-23	KHI-YYZ	Delayed	Technical	6	4	Engine Vibration Warning
PIA227	A320-200	6-10-23	KHI-JED	Delayed	Technical	5	2	Engine Oil Leak
PIA522	A320-200	6-10-23	LHE-ISB	Cancelled	External			Mass Fuel Shortages
PK305	A320-200	6-10-23	LHE-KHI	Cancelled	External			Mass Fuel Shortages
PIA135	B777-200ER	7-10-23	ISB-LHE	Cancelled	External			Mass Fuel Shortages
PK304	B777-200ER	7-10-23	KHI-LHE	Cancelled	External			Mass Fuel Shortages
PIA145	A320-200	7-10-23	ISB-KUL	Delayed	External	5		Mass Fuel Shortages
PIA721	A320-200	8-10-23	LHE-SHJ	Delayed	External	6		Mass Fuel Shortages
PIA976	A320-200	8-10-23	KHI-BAH	Delayed	External	4		Mass Fuel Shortages
PIA210	B777-200ER	10-10-23	KHI-ISB	Cancelled	External	7		Mass Fuel Shortages
PIA419	B777-200ER	10-10-23	MUX-KHI	Cancelled	External	6		Mass Fuel Shortages
PIA279	A320-200	13-10-23	LHE-KWI	Delayed	External	6	4	Mass Fuel Shortages
PIA309	A320-200	13-10-23	LHE-KHI	Delayed	External	5		Mass Fuel Shortages
PIA540	ATR42-500	18-10-23	KHI-GWD	Cancelled	External	3		Mass Fuel Shortages
PIA121	ATR42-500	18-10-23	PEW-CJL	Cancelled	Technical	2	0.4	Ground Power Unite Failure
PK300	B777-200ER	18-10-23	ISB-YYZ	Delayed	Technical	7	4	Autopilot Malfunction
PIA211	A320-200	30-11-23	KHI-ISB	Delayed	Technical	3	0.9	Fluctuating N1/N2 reading
PIA123	B777-200ER	7-12-23	KHI-KUL	Delayed	Technical		4.9	Flap Asymmetry warning
PIA854	A320-200	17-12-23	KHI-DXB	Delayed	Technical	2	0.2	Cockpit window fogging
PIA973	A320-200	21-12-23	KHI-DOH	Delayed	Technical	2.5	0.06	Seatbelt light circuit failure
	1	1	1	1	I	1	1	

PIA278	A320-200	28-12-23	KWI-LHE	Delayed	Technical	0	0.1	IFE System Failure
PIA465	A320-200	20-12-23	KHI-MUX	Delayed	Crew-Related	4	0	Fight Amongst Cabin Crew
PIA575	ATR42-500	3-1-24	SKZ-GWD	Delayed	Technical		2	Hydraulic Fluid Leak
PIA789	B777-200ER	6-2-24	LHE-YYZ	Delayed	Technical	3	0.5	GPS Signal Error
PIA800	A320-200	4-3-24	ISB-DXB	Delayed	Technical	3	1.9	Engine Vibration Warning
PIA540	ATR42-500	16-4-24	KHI-GWD	Delayed	External			Unassessable runway
PK300	B777-200ER	15-5-24	ISB-YYZ	Delayed	Technical	2	1	Yaw Damper Fault
PIA522	A320-200	31-5-24	LHE-ISB	Delayed	Technical	2	0.5	Air conditioning failure
PIA790	B777-200ER	18-6-24	YYZ-LHE	Delayed	Technical	1	0.05	Seatbelt light circuit failure
PIA134	A320-200	5-7-24	KHI-ISB	Delayed	Technical	3	1.9	Engine Vibration Warning
PIA622	A320-200	28-7-24	KHI-UET	Delayed	Operational	3		Late Boarding
PIA540	A320-200	13-8-24	KHI-GWD	Delayed	Technical	2	1	Yaw Damper Fault
PK301	B777-200ER	25-8-24	YYZ-ISB	Delayed	Technical	2	0.5	Air conditioning failure
PIA541	ATR42-500	1-9-24	GWD-KHI	Delayed	Technical	1	0.05	Seatbelt light circuit failure
PK304	A320-200	6-9-24	KHI-LHE	Delayed	Technical	3	0.5	Air conditioning failure
PIA789	B777-200ER	10-9-24	LHE-YYZ	Delayed	Technical	5	1.5	Unusual Engine noise during taxi
PIA783	B777-200ER	21-9-24	KHI-YYZ	Delayed	Technical	7	4	Autopilot Malfunction
PIA279	A320-200	2-10-24	LHE-KWI	Delayed	Technical	3	0.9	Fluctuating N1/N2 reading
PIA121	ATR42-500	14-10-24	PEW-CJL	Delayed	Bird Strike	6	0.5	Bird Strike
PIA692	B777-200ER	19-11-24	ISB-GIL	Delayed	Technical	0	0.1	IFE System Failure
PIA824	A320-200	25-11-24	LHE-UET	Delayed	Technical	4	0	Fight Amongst Cabin Crew
PIA124	B777-200ER	1-12-24	KUL-KHI	Delayed	External	5	0.4	Labor Disputes
PIA540	ATR42-500	6-12-24	KHI-GWD	Delayed	Operational	1.5		Late Boarding
PIA575	ATR42-500	21-12-24	GWD-SKZ	Delayed	Technical	5	1.9	Engine Overheating
PK300	B777-200ER	26-12-24	ISB-YYZ	Delayed	Technical	2	1	Yaw Damper Fault
					•			

PIA110	A320-200	30-12-24	LHE-PEW	Delayed	Operational	1	Late Boarding