

These systems can not be controlled aggressivly because they can get unstable. It can be seen in the s-plane because the poles travell to the RHP zeros with the increase of K. But also in the Bode-Plat it is notisable because the zeros reduce the Phasemargin.