

Inspection Report IR-2026-013 - Pressure Vessel V-210

Facility: BCR, Unit 5 - Hydrotreater. Date: 02-09-2026. Inspector: A. Kulkarni (INSP-0455).

1. Scope

Ultrasonic thickness survey of shell courses at four thickness measurement points (TP1-TP4).

2. Measurements

Point	Location	Thickness (mm)	Min allowable (mm)	Result
TP1	Shell course 1, 6 o'clock	5.4	5.0	OK
TP2	Shell course 1, 12 o'clock	5.2	5.0	OK
TP3	Shell course 2, 6 o'clock	4.8	5.0	BELOW MINIMUM
TP4	Shell course 2, 12 o'clock	5.1	5.0	OK

3. Findings

TP3 reads 4.8 mm, below the 5.0 mm minimum allowable thickness. Under SOP-01 this requires engineering review and a fitness-for-service assessment (SOP-06). Localised corrosion under insulation is suspected near TP3.

4. Recommendation

Escalate to the Mechanical Engineering Manager for a continued-operation decision. Increase monitoring frequency.

SYNTHETIC DEMO DOCUMENT - fictional company, invented data. Not for operational use.