Quality alert rules for the ring frame floor

Revision 3 · approved by the QC manager · applies to all shifts

Who is told when a test fails

1. When a lab test fails, alert the shift supervisor of that frame at once.
2. If nobody answers within 4 minutes, alert the backup supervisor on the same shift.
3. If nobody answers within 8 minutes, alert the QC manager.
4. If nobody answers within 15 minutes, call the plant head.

Test limits

5. 30s count must stay between 29.5 and 30.5 Ne. Critical.
6. 40s count must stay between 39.2 and 40.8 Ne. Critical.
7. 30s CSP minimum 2250. Major.
8. 20s twist must stay between 17 and 19 TPI. Minor.

Fixing

9. Every fix needs a lab re-test before the alert is closed.
10. Fitters must log the machine part that was repaired.
11. Keep the old cops of a failed frame aside until the shift ends.