



Document generator

Property Inspection Report - Structurebase

Routine condition review

Document	INSP-2026-012
Issue date	2026-04-22
Property	Lekki Phase 1 Detached Villa
Address	Adebayo Doherty Road, Lekki Phase 1, Lagos
Inspection date	2026-04-22
Inspected by	Operations Supervisor
Inspected for	Property Owner Private Client

Summary

The property remains market-ready with minor corrective work required in the guest bathroom and power-backup enclosure.

Interior spaces

Area	Condition	Status	Note
Living room	Good	Serviceable	Paint finish and lighting points remain in order.
Guest bathroom	Fair	Attention required	Mixer tap looseness observed at sink.

External and plant

Area	Condition	Status	Note
Generator enclosure	Fair	Attention required	Ventilation louvre requires cleaning and panel fasteners need review.

Recommendations

- Tighten and re-test the guest bathroom mixer assembly before the next viewing cycle.
- Complete generator enclosure cleaning and confirm ventilation airflow.

Inspected by
Operations Supervisor
Structurebase

Acknowledged by
Property Owner
Client