Date Submitted: 10/26/19

Goals:

- Interface the given MPU6050 IMU using I2C protocol to TivaC. Print all accelerometer and gyro values on to the serial terminal.
- Interface the given MPU6050 IMU using I2C protocol to TivaC. Plot all accelerometer and gyro values on to a Graph (you can use any graphing tool).
- Implement a complementary filter to filter the raw accelerometer and gyro values. Print all raw and filtered accelerometer and gyro values on to the serial terminal. Implement the filter using IQMath Library.
- : Implement a complementary filter to filter the raw accelerometer and gyro values. Plot all raw and filtered accelerometer and gyro values on to a Graph (you can use any graphing tool).

Deliverables: The deliverables of this midterm are an interfaced MPU6050 with i2c to communicate with the TIVA C. In task 1, students will communicate the gyroscopic and acceleration values to the TIVA C then display those values using UART and in graph form in task 2. In task 3 & 4, we will add a complimentary filter using IQmath to the raw gyroscopic and acceleration values which we will display to the UART terminal and graph.

Components:

MPU 6050:

- Motion tracking sensor for 3 axis gyroscopic, 3 axis acceleration, and temperature uses
- Has a voltage regulator for its 3.3v power
- Interfaced with i2c
- Connected SDA to PB3 & SCL to PB2

TIVA C TM4C123GH6PM:

- Microcontroller used in a variety of applications
- 32-bit ARM Cortex-M4 80 MHz processor

I2C:

- Protocol to allow multiple "slave" digital integrated circuits to communicate with "master" chips
- Used for short distance communication, limited use in long distance
- Can communicate at 100kHz or 400kHz

IQ Math:


- Allows users to calculate math in an optimal and efficient way
- Works with fixed point numbers
- Used to convert the float number into a 16 bit num for the complimentary filter

Implementation: Described in the comments of the code.

Task 01:

Youtube Link: https://youtu.be/x3mtSJX5cBo

Modified Schematic (if applicable):



Screenshot of output:

```
■ <Closed > COM5 
□
Acc. X: -13345 | Acc. Y: -1997 | Acc. Z: 13584
Gyro. X: -26 | Gyro. Y: -2 | Gyro. Z: 17
Acc. X: -13407 | Acc. Y: -1983 | Acc. Z: 13699
Gyro. X: -14 | Gyro. Y: 0 | Gyro. Z: 20
Acc. X: -13249 | Acc. Y: -1973 | Acc. Z: 13450
Gyro. X: -12 | Gyro. Y: Acc. X: 13785 | Acc. Y: -1714 | Acc. Z: 13824
Gyro. X: 50 | Gyro. Y: 18 | Gyro. Z: 43
Acc. X: -13685 | Acc. Y: -1978 | Acc. Z: 13009
Gyro. X: -16 | Gyro. Y: 0 | Gyro. Z: 15
Acc. X: -33721 | Acc. Y: -7381 | Acc. Z: 23811
Gyro. X: 4365 | Gyro. Y: 2832 | Gyro. Z: 683
Acc. X: -10518 | Acc. Y: -4732 | Acc. Z: 9795
Gyro. X: 587 | Gyro. Y: 960 | Gyro. Z: 1037
Acc. X: -14164 | Acc. Y: -239 | Acc. Z: 13014
Gyro. X: -21 | Gyro. Y: -2 | Gyro. Z: 19
Acc. X: -14039 | Acc. Y: -296 | Acc. Z: 12870
Gyro. X: -17 | Gyro. Y: 0 | Gyro. Z: 20
Acc. X: -14097 | Acc. Y: -354 | Acc. Z: 12827
Gyro. X: -9 | Gyro. Y: 0 | Gyro. Z: 20
Acc. X: -13962 | Acc. Y: -301 | Acc. Z: 12923
Gyro. X: -13 | Gyro. Y: -3 | Gyro. Z: 20
Modified Code:
int main(void)
#include <stdbool.h>
#include <stdint.h>
#include <stdlib.h>
#include <stdio.h>
#include <stdarg.h>
#include <stdbool.h>
#include "sensorlib/i2cm drv.h"
#include "sensorlib/hw mpu6050.h"
#include "sensorlib/mpu6050.h"
#include "inc/hw ints.h"
#include "inc/hw memmap.h"
#include "inc/hw_sysctl.h"
#include "inc/hw_types.h"
#include "inc/hw_i2c.h"
#include "inc/hw types.h"
#include "inc/hw gpio.h"
#include "driverlib/gpio.h"
#include "driverlib/pin_map.h"
```

```
#include "driverlib/rom.h"
#include "driverlib/rom_map.h"
#include "driverlib/debug.h"
#include "driverlib/interrupt.h"
#include "driverlib/i2c.h"
#include "driverlib/sysctl.h"
#include "driverlib/uart.h"
#include "utils/uartstdio.h"
#include "utils/uartstdio.h"
#include "driverlib/uart.h"
#define ACCELEROMETER_SENSITIVITY 8192.0
#define GYROSCOPE SENSITIVITY 65.536
#define SAMPLE_RATE 0.01
void ConfigureUART(void) { //config uart to output accel & gyro values
    SysCtlPeripheralEnable(SYSCTL PERIPH GPIOA);
    SysCtlPeripheralEnable(SYSCTL PERIPH UART0);
    GPIOPinConfigure(GPIO PA0 U0RX);
    GPIOPinConfigure(GPIO_PA1_U0TX);
    GPIOPinTypeUART(GPIO_PORTA_BASE, GPIO_PIN_0 | GPIO_PIN_1);
    UARTClockSourceSet(UART0_BASE, UART_CLOCK_PIOSC);
    UARTStdioConfig(0, 115200, 16000000);
}
// A boolean that is set when a MPU6050 command has completed.
volatile bool g_bMPU6050Done;
//
// I2C master instance
tI2CMInstance g_sI2CMSimpleInst;
// The function that is provided by this example as a callback when MPU6050
// transactions have completed.
//
void MPU6050Callback(void *pvCallbackData, uint_fast8_t ui8Status)
    // See if an error occurred.
    if (ui8Status != I2CM_STATUS_SUCCESS)
    {
        // An error occurred, so handle it here if required.
       //
    }
    // Indicate that the MPU6050 transaction has completed.
    g_bMPU6050Done = true;
```

```
}
void InitI2C0(void)
    //enable I2C module 0
    SysCtlPeripheralEnable(SYSCTL_PERIPH_I2C0);
    //reset module
    SysCtlPeripheralReset(SYSCTL PERIPH I2C0);
    //enable GPIO peripheral that contains I2C 0
    SysCtlPeripheralEnable(SYSCTL_PERIPH_GPIOB);
    // Configure the pin muxing for I2CO functions on port B2 and B3.
    GPIOPinConfigure(GPIO_PB2_I2C0SCL);
    GPIOPinConfigure(GPIO PB3 I2C0SDA);
    // Select the I2C function for these pins.
    GPIOPinTypeI2CSCL(GPIO PORTB BASE, GPIO PIN 2);
    GPIOPinTypeI2C(GPIO_PORTB_BASE, GPIO_PIN_3);
    // Enable and initialize the I2CO master module. Use the system clock for
    // the I2C0 module.
    // I2C data transfer rate set to 400kbps.
    I2CMasterInitExpClk(I2C0_BASE, SysCtlClockGet(), true);
    //clear I2C FIFOs
    HWREG(I2C0\_BASE + I2C\_0\_FIFOCTL) = 80008000;
    // Initialize the I2C master driver.
    I2CMInit(&g_sI2CMSimpleInst, I2C0_BASE, INT_I2C0, 0xff, 0xff, SysCtlClockGet());
}
//
// The interrupt handler for the I2C module.
void I2CMSimpleIntHandler(void)
{
    // Call the I2C master driver interrupt handler.
    I2CMIntHandler(&g_sI2CMSimpleInst);
}
void delayMS(int ms) {
    SysCtlDelay( (SysCtlClockGet()/(3*1000))*ms ); // less accurate
}
void MPU6050Code(void) {
    float fAccel[3], fGyro[3];
    float aAccel = 0, bAccel = 0, cAccel = 0;
    float aGyro = 0, bGyro = 0, cGyro = 0;
    tMPU6050 sMPU6050;
```

```
//
    // Initialize the MPU6050. This code assumes that the I2C master instance
    // has already been initialized.
    //
    g_bMPU6050Done = false;
    MPU6050Init(&sMPU6050, &g sI2CMSimpleInst, 0x68, MPU6050Callback, &sMPU6050);
    while (!g_bMPU6050Done);
    // Configure the MPU6050 for +/- 4 g accelerometer range.
    //
    //Settings for the Accelerometer
    g bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_O_ACCEL_CONFIG, // Accelerometer configuration
                           0xFF,//~MPU6050_ACCEL_CONFIG_AFS_SEL_M, // No need to mask
                           MPU6050_ACCEL_CONFIG_AFS_SEL_4G, // Accelerometer full-
scale range 4g
                           MPU6050Callback,
                           &sMPU6050);
    while (!g_bMPU6050Done);
    g_bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_O_GYRO_CONFIG, // Gyroscope configuration
                           0xFF, // No need to mask
                           MPU6050_GYRO_CONFIG_FS_SEL_250, // Gyro full-scale range
+/- 250 degrees/sec
                           MPU6050Callback,
                           &sMPU6050);
    while (!g_bMPU6050Done);
    g bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_O_PWR_MGMT_1, // Power management 1 register
                           0x00,//0x02 & MPU6050_PWR_MGMT_1_DEVICE_RESET,
                           MPU6050Callback,
                           &sMPU6050);
    while (!g_bMPU6050Done);
    g bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_O_PWR_MGMT_2, // Power management 2 register
                           0x00,
                           0x00,
                           MPU6050Callback,
                           &sMPU6050);
    while (!g bMPU6050Done);
    //
    // Loop forever reading data from the MPU6050. Typically, this process
    // would be done in the background, but for the purposes of this example,
    // it is shown in an infinite loop.
    //
```

```
while (1)
    {
        //
        // Request another reading from the MPU6050.
        //
        g bMPU6050Done = false;
        MPU6050DataRead(&sMPU6050, MPU6050Callback, &sMPU6050);
        while (!g bMPU6050Done)
        }
        //
        // Get the new accelerometer and gyroscope readings.
        MPU6050DataAccelGetFloat(&sMPU6050, &fAccel[0], &fAccel[1], &fAccel[2]);
        MPU6050DataGyroGetFloat(&sMPU6050, &fGyro[0], &fGyro[1], &fGyro[2]);
        // Do something with the new accelerometer and gyroscope readings.
        aGyro = fGyro[0] * 1000; //multiply by 1000 to see the value better
        bGyro = fGyro[1] * 1000;
        cGyro = fGyro[2] * 1000;
        aAccel = fAccel[0] * 1000;
        bAccel = fAccel[1] * 1000;
        cAccel = fAccel[2] * 1000;
        UARTprintf("Acc. X: %d | Acc. Y: %d | Acc. Z: %d\n", (int)aAccel,
(int)bAccel, (int)cAccel); //print data
        UARTprintf("Gyro. X: %d | Gyro. Y: %d | Gyro. Z: %d\n", (int)aGyro,
(int)bGyro, (int)cGyro);
        UARTprintf("\n");
        delayMS(1000);
    }
}
int main(void)
    SysCtlClockSet(SYSCTL SYSDIV 5|SYSCTL USE PLL|SYSCTL OSC MAIN|SYSCTL XTAL 16MHZ);
    InitI2C0();
    ConfigureUART();
    MPU6050Code();
    while(1)
    {
    }
}
```

Task 02:

Youtube Link: https://youtu.be/pMkw7X2Cd8k



The first column from top to bottom is:

aGyro, bGyro, cGyro

The second column from top to bottom is:

aAccel, bAccel, cAccel

Modified Code:

The same code as task 1

.....

Task 03:

```
\cc. X: -354 | Acc. Y: 19969 | Acc. Z: -62
3yro. X: -26 | Gyro. Y: -15 | Gyro. Z: -52
itch: 0 Roll: 90
Acc. X: 153 | Acc. Y: 20089 | Acc. Z: -215
3yro. X: -13 | Gyro. Y: 27 | Gyro. Z: -102
itch: 0 Roll: 90
Acc. X: 3602 | Acc. Y: 18029 | Acc. Z: -2088
3yro. X: -286 | Gyro. Y: -238 | Gyro. Z: 437
Pitch: 123 Roll: 96
Acc. X: 17660 | Acc. Y: 8277 | Acc. Z: 3151
Gyro. X: -790 | Gyro. Y: -108 | Gyro. Z: 926
itch: 79 Roll: 69
Acc. X: 21253 | Acc. Y: 2600 | Acc. Z: 2826
3yro. X: 199 | Gyro. Y: -176 | Gyro. Z: 317
Pitch: 84 Roll: 45
Acc. X: 20161 | Acc. Y: 967 | Acc. Z: 2203
3yro. X: -29 | Gyro. Y: -8 | Gyro. Z: -20
Pitch: 84 Roll: 0
Acc. X: 20367 | Acc. Y: 900 | Acc. Z: 2136
3yro. X: -32 | Gyro. Y: -21 | Gyro. Z: -17
Youtube Link: <a href="https://youtu.be/sIMX9TLPqHE">https://youtu.be/sIMX9TLPqHE</a>
Modified Code:
#include <stdbool.h>
#include <stdint.h>
#include <stdlib.h>
#include <stdio.h>
#include <stdarg.h>
#include <stdbool.h>
#include "sensorlib/i2cm_drv.h"
#include "sensorlib/hw mpu6050.h"
#include "sensorlib/mpu6050.h"
#include "inc/hw ints.h"
#include "inc/hw_memmap.h"
#include "inc/hw_sysctl.h"
#include "inc/hw_types.h"
#include "inc/hw_i2c.h"
#include "inc/hw types.h"
#include "inc/hw_gpio.h"
#include "driverlib/gpio.h"
#include "driverlib/pin_map.h"
#include "driverlib/rom.h"
#include "driverlib/rom_map.h"
#include "driverlib/debug.h"
#include "driverlib/interrupt.h"
#include "driverlib/i2c.h"
#include "driverlib/sysctl.h"
#include "driverlib/uart.h"
#include "uartstdio.h"
#include "driverlib/uart.h"
#include "math.h"
```

```
#include "IQmathLib.h"
#define ACCELEROMETER SENSITIVITY 8192.0
#define GYROSCOPE SENSITIVITY 65.536
#define SAMPLE_RATE 0.01
#define dt 0.01 // 10 ms sample rate!
void ComplementaryFilter(short accData[3], short gyrData[3], float *pitch, float
*roll)
    float pitchAcc, rollAcc;
    // Integrate the gyroscope data -> int(angularSpeed) = angle
    // Angle around the X-axis
    *pitch += ((float)gyrData[0] / GYROSCOPE_SENSITIVITY) * dt;
    // Angle around the Y-axis
    *roll += ((float)gyrData[1] / GYROSCOPE SENSITIVITY) * dt;
    // Compensate for drift with accelerometer data
    // Sensitivity = -2 to 2 G at 16Bit -> 2G = 32768 && 0.5G = 8192
    int forceMagnitudeApprox = abs(accData[0]) + abs(accData[1]) + abs(accData[2]);
    if (forceMagnitudeApprox > 8192 && forceMagnitudeApprox < 32768)</pre>
    {
        // Turning around the X axis results in a vector on the Y-axis
        pitchAcc = atan2f((float)accData[1], (float)accData[2]) * 180 / M_PI;
        *pitch = *pitch * 0.98 + pitchAcc * 0.02;
        // Turning around the Y axis results in a vector on the X-axis
        rollAcc = atan2f((float)accData[0], (float)accData[2]) * 180 / M PI;
        *roll = *roll * 0.98 + rollAcc * 0.02;
    }
}
void ConfigureUART(void) {
    SysCtlPeripheralEnable(SYSCTL_PERIPH_GPIOA);
    SysCtlPeripheralEnable(SYSCTL PERIPH UART0);
    GPIOPinConfigure(GPIO_PA0_U0RX);
    GPIOPinConfigure(GPIO PA1 U0TX);
    GPIOPinTypeUART(GPIO_PORTA_BASE, GPIO_PIN_0 | GPIO_PIN_1);
    UARTClockSourceSet(UART0_BASE, UART_CLOCK_PIOSC);
    UARTStdioConfig(0, 115200, 16000000);
}
volatile bool g_bMPU6050Done;
tI2CMInstance g_sI2CMSimpleInst;
void MPU6050Callback(void *pvCallbackData, uint_fast8_t ui8Status)
{
    if (ui8Status != I2CM STATUS SUCCESS) {}
    g bMPU6050Done = true;
}
void InitI2C0(void)
    //enable I2C module 0
    SysCtlPeripheralEnable(SYSCTL PERIPH I2C0);
```


```
//reset module
    SysCtlPeripheralReset(SYSCTL_PERIPH_I2C0);
    //enable GPIO peripheral that contains I2C 0
    SysCtlPeripheralEnable(SYSCTL PERIPH GPIOB);
    // Configure the pin muxing for I2CO functions on port B2 and B3.
    GPIOPinConfigure(GPIO PB2 I2C0SCL);
    GPIOPinConfigure(GPIO_PB3_I2C0SDA);
    // Select the I2C function for these pins.
    GPIOPinTypeI2CSCL(GPIO PORTB BASE, GPIO PIN 2);
    GPIOPinTypeI2C(GPIO_PORTB_BASE, GPIO_PIN_3);
    // Enable and initialize the I2CO master module. Use the system clock for
    // the I2C0 module.
    // I2C data transfer rate set to 400kbps.
    I2CMasterInitExpClk(I2C0 BASE, SysCtlClockGet(), true);
    //clear I2C FIFOs
    HWREG(I2C0\_BASE + I2C\_0\_FIFOCTL) = 80008000;
    // Initialize the I2C master driver.
    I2CMInit(&g sI2CMSimpleInst, I2C0 BASE, INT I2C0, 0xff, 0xff, SysCtlClockGet());
}
void I2CMSimpleIntHandler(void)
{
    I2CMIntHandler(&g_sI2CMSimpleInst);
}
void delayMS(int ms) {
    SysCtlDelay( (SysCtlClockGet()/(3*1000))*ms ); // less accurate
}
int main(void)
    SysCtlClockSet(SYSCTL_SYSDIV_5|SYSCTL_USE_PLL|SYSCTL_OSC_MAIN|SYSCTL_XTAL_16MHZ);
    InitI2C0():
    ConfigureUART();
    float pitch, roll, tempPitch, tempRoll;
    float fAccel[3], fGyro[3];
    float xAccel = 0, yAccel = 0, zAccel = 0;
    float xGyro = 0, yGyro = 0, zGyro = 0;
    _iq16 qAccel[3], qGyro[3];
    tMPU6050 sMPU6050;
    // Initialize the MPU6050. This code assumes that the I2C master instance
    // has already been initialized.
    //
    g bMPU6050Done = false;
```

```
MPU6050Init(&sMPU6050, &g sI2CMSimpleInst, 0x68, MPU6050Callback, &sMPU6050);
    while (!g bMPU6050Done);
    //
    // Configure the MPU6050 for +/- 4 g accelerometer range.
    //
    //Settings for the Accelerometer
    g bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_O_ACCEL_CONFIG, // Accelerometer configuration
                           0xFF,//~MPU6050_ACCEL_CONFIG_AFS_SEL_M, // No need to mask
                           MPU6050_ACCEL_CONFIG_AFS_SEL_4G, // Accelerometer full-
scale range 4g
                           MPU6050Callback,
                           &sMPU6050);
    while (!g bMPU6050Done);
    g bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050 O GYRO CONFIG, // Gyroscope configuration
                           0xFF, // No need to mask
                           MPU6050_GYRO_CONFIG_FS_SEL_250, // Gyro full-scale range
+/- 250 degrees/sec
                           MPU6050Callback,
                           &sMPU6050);
    while (!g bMPU6050Done);
    g_bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_0_PWR_MGMT_1, // Power management 1 register
                           0x00,
                           0x00,//0x02 & MPU6050 PWR MGMT 1 DEVICE RESET,
                           MPU6050Callback,
                           &sMPU6050);
    while (!g_bMPU6050Done);
    g_bMPU6050Done = false;
    MPU6050ReadModifyWrite(&sMPU6050,
                           MPU6050_O_PWR_MGMT_2, // Power management 2 register
                           0x00,
                           0x00.
                           MPU6050Callback,
                           &sMPU6050);
    while (!g_bMPU6050Done);
    // Loop forever reading data from the MPU6050. Typically, this process
    // would be done in the background, but for the purposes of this example,
    // it is shown in an infinite loop.
    //
   while (1)
    {
        // Request another reading from the MPU6050.
        //
```

g bMPU6050Done = false;

```
MPU6050DataRead(&sMPU6050, MPU6050Callback, &sMPU6050);
        while (!g bMPU6050Done)
        }
        //
        // Get the new accelerometer and gyroscope readings.
        MPU6050DataAccelGetFloat(&sMPU6050, &fAccel[0], &fAccel[1], &fAccel[2]);
        MPU6050DataGyroGetFloat(&sMPU6050, &fGyro[0], &fGyro[1], &fGyro[2]);
        // Do something with the new accelerometer and gyroscope readings.
        xAccel = fAccel[0] * 1000;
        yAccel = fAccel[1] * 1000;
        zAccel = fAccel[2] * 1000;
        xGyro = fGyro[0] * 1000;
        yGyro = fGyro[1] * 1000;
        zGyro = fGyro[2] * 1000;
        short fAccelShort[3];
        fAccelShort[0] = (short)fAccel[0];
        fAccelShort[1] = (short)fAccel[1];
        fAccelShort[2] = (short)fAccel[2];
        short fGryoShort[3];
        fGryoShort[0] = (short)fGyro[0];
        fGryoShort[1] = (short)fGyro[1];
        fGryoShort[2] = (short)fGyro[2];
        qAccel[0] = _IQ16(fAccel[0]);
        qAccel[1] = _IQ16(fAccel[1]);
        qAccel[2] = _IQ16(fAccel[2]);
        qGyro[0] = IQ16(fGyro[0]);
        qGyro[1] = IQ16(fGyro[1]);
        qGyro[2] = _IQ16(fGyro[2]);
        ComplementaryFilter(&qAccel[0], &qGyro[0], &pitch, &roll); //filter values
        UARTprintf("Acc. X: %d | Acc. Y: %d | Acc. Z: %d\n", (int)xAccel,
(int)yAccel, (int)zAccel);
        UARTprintf("Gyro. X: %d | Gyro. Y: %d | Gyro. Z: %d\n", (int)xGyro,
(int)yGyro, (int)zGyro);
        UARTprintf("Roll: %d", (int)roll);
        UARTprintf("\n");
        //UARTprintf("test\n");
        delayMS(1000);
    }
}
```

Task 04:



Left pic: pitch right pic: roll

Youtube Link: https://youtu.be/cjacm6v9m_o

Modified Schematic (if applicable):

Modified Code:

Same code as above

Conclusion:

I was able to complete all tasks. The first two tasks involved getting the raw gyro and accelerometer files from the mpu 6050 using i2c. The last two tasks involved filtering the raw gyro and accel values then print those using uart and in the graph.