

Upgrade steps:

- 1. The PC computer and XDM2041 connected by RS232 cable (you have to choose a PC has RS232 port)
- 2. Install the driver, there is a driver instruction. (PC software USB driver install guide), pleae follow it to install the driver.
- 3. Double click DS_Wave_Patch_1.17.7.v20191126_Setup.exe
- 4. Choose the corresponding COM (you can go to PC management to look for the corresponding COM), see below screenshot



5. Choose OS and the file of

XDM1041 OS V2.1.2 20210525.bin



- 6. Turn off the XDM2041 and then turn it on
- 7. Choose "begin to download" to begin the upgrade
- 8. After upgrade, the version number is V