IA9100 DRAFT 8.1 k · FOD · STRENGTHENED

# FOD: from the poster into the plan

In the draft, operations are planned to prevent, detect and mitigate foreign objects and debris.

1. Name FOD in the PFMEA where it can occur
2. Put a check in the control plan at those steps
3. Train the people in FOD areas, with a date
4. Keep the FOD procedure current
5. Look where debris actually hides

Swipe: one action per page, with the record that proves it.

ACTION 1 OF 5 · DRAFT 8.1 k

STRENGTHENED IN THE DRAFT

# Name FOD in the PFMEA where it can occur

Deburr, wash, assembly, packing: give each operation where debris can be left its own failure-mode line.

## THE RECORD THAT PROVES IT

- ☐ A PFMEA line naming FOD, operation by operation

**Watch for:** One generic FOD line at the front of the PFMEA, not at the operations where it happens.

ACTION 2 OF 5 · DRAFT 8.1 k

STRENGTHENED IN THE DRAFT

# Put a check in the control plan at those steps

A control or a check against FOD at each step the PFMEA names: a blow-out, a borescope check, a clean-area sign-off.

## THE RECORD THAT PROVES IT

- ☐ A control plan row for each FOD line

> **In the draft:** Operations are planned to prevent, detect and mitigate foreign objects and debris.

ACTION 3 OF 5 · DRAFT 8.1 k

STRENGTHENED IN THE DRAFT

# Train the people in FOD areas, with a date

Everyone who works where debris can get into the product, second shift and temporary staff included.

## THE RECORD THAT PROVES IT

- ☐ The training matrix: a FOD line with a date and a refresh interval

> **Sample plant:** FOD prevention is on the training matrix for three assemblers; one hasn't started.

ACTION 4 OF 5 · DRAFT 8.1 k

STRENGTHENED IN THE DRAFT

# Keep the FOD procedure current

Review it against the PFMEA lines and the control plan rows, so all three describe the same controls.

THE RECORD THAT PROVES IT

- ☐ The FOD procedure, with its revision and next review date

> **Sample plant:** Its FOD procedure, QP-7.1.4 Work Environment and FOD, is at Rev 6 and current.

ACTION 5 OF 5 · DRAFT 8.1 k

STRENGTHENED IN THE DRAFT

# Look where debris actually hides

Chips in blind holes and cross-drilled passages, blast media, deburr debris, tape and caps, and tools left in assemblies.

## THE RECORD THAT PROVES IT

- ☐ Each one named on the PFMEA line for its operation

**Watch for:** Final inspection as the only control: it finds debris after it is already in the part.

SAMPLE PLANT · WHERE FOD SHOWS UP

# In the procedure. Not yet in the plan.

**Procedure**
QP-7.1.4 Work Environment and FOD, Rev 6, current

**Training**
FOD prevention on three assemblers' records; one not started

**PFMEA**
No line names FOD or debris on any operation

**Control plan**
No row checks for FOD

**The gap:** FOD never made it into planning. The fix is a PFMEA line and a control plan row for each operation where it can occur.

THIS WEEK

# Pick one. Keep the record.

1. **Find the operations where debris can be left**
   PFMEA lines, by operation
2. **Add a check at each one**
   Control plan rows
3. **Date the training of the people there**
   Training matrix

TELL ME IN THE COMMENTS

## Where in your shop would an auditor find FOD in the plan, not just on the poster?

A worksheet for this check:
**book.aegistechnologies.tech/w/ia9100-fod-planning**

IA9100 is not yet final. Clauses are from the IAQG's published key-change summaries (November 2023), as the draft numbers them.