RASPBERRY PI ZERO POWER SENSOR HAT

TABLE OF CONTENTS

SHEET	SHEET NAME
1	TITLE_TOC
2	BLOCK_DIAGRAM
3	LIPO_CHARGER_AND_BCM_RESET
4	POWER_ENTRY_BOOST_LDO
5	SENSORS
6	PI_MCU_CONNECT_AND_MOUNTING
7	ASSEMBLY_COMPONENTS
8	
9	
10	

DESIGN: 001-001-01

TEAM: P17105


ENGINEER: CHRIS SCHWAB


TITLE_TOC


TITLE: raspi_zero_power_sensor_hat


Document Number: REV:
1


Date: not saved! Sheet: 1/7











CONNECTOR ASSEMBLY and EXTERNAL SENSORS J301: 5V Charger Input 3x 12mm Nylon Standoffs (Top Righ, Bottom Right, Bottom Left) Not listed on BOM, enough for 6 HATs (Amazon: B01HBYDH70) J401: 1-cell Li-Ion Battery Input 2500mAh/2000mAh 3.7V Battery ordered from Adafruit (Part Number: 328/2011) J402: Battery Jumper J601: RasPi Power/GPIO Header BOM710 HEADER-RECT-MALE-2X5 'Digi-key J602: MCU IO Digi-key Digi-key Digi-key Digi-key J603: 1-Wire Temperature Sensor J604: RasPi Reset/GPIO Header BOM722 HEADER-RECT-MALE-2X3 Digi-key 952-2120-ND ASSEMBLY_COMPONENTS TITLE: raspi_zero_power_sensor_hat Document Number: Sheet: 7/7 Date: not saved!