

FIG. 1. The thermal forming process under investigation. The process can be divided into four steps: (a) sheet heating, (b) dropping of the assist-plug, (c) vacuum forming, and (d) removal of product from the mold.