ROOF CONDITION CERTIFICATION REPORT

Prepared for: Hill Country Hospitality Partners, LLC

Inspection Date: 02/10/2026

Report Date: 03/15/2026

Insured Hill Country Hospitality Partners, LLC	Policy Number CP-HCHP-2025-3352
Address 604 Brazos Street	City, State, ZIP Austin, TX 78701
SIC Code 7011	Inspector L. Thompson, CSP

OVERALL RISK GRADE: PPC 5

Grading Scale: ISO Public Protection Class

LOCATIONS INSPECTED

Location 1: The Driskill Austin
Address: 604 Brazos Street, Austin, TX 78701
Construction: Fire Resistive • Year Built: 2010 • Stories: 8 • Sprinklered: Yes • Protection Class: 5

Location 2: Riverwalk Suites San Antonio
Address: 112 College Street, San Antonio, TX 78205
Construction: Fire Resistive • Year Built: 2006 • Stories: 12 • Sprinklered: Yes • Protection Class: 2

Location 3: Fredericksburg Inn & Spa
Address: 245 East Main Street, Fredericksburg, TX 78624
Construction: Masonry Non-Combustible • Year Built: 1998 • Stories: 3 • Sprinklered: Yes • Protection Class: 1

Location 4: South Congress Motor Hotel
Address: 1220 South Congress Avenue, Austin, TX 78704
Construction: Masonry Non-Combustible • Year Built: 2015 • Stories: 4 • Sprinklered: Yes • Protection Class: 2

Location 5: Blanco River Steakhouse
Address: 608 Brazos Street, Austin, TX 78701
Construction: Fire Resistive • Year Built: 2010 • Stories: 1 • Sprinklered: Yes • Protection Class: 2

Location 6: The Oasis at Lake Travis
Address: 6550 Comanche Trail, Austin, TX 78732
Construction: Non-Combustible • Year Built: 2012 • Stories: 2 • Sprinklered: Yes • Protection Class: 5

Location 7: Mission Cantina - Pearl District
Address: 303 Pearl Parkway, San Antonio, TX 78215
Construction: Joisted Masonry • Year Built: 2014 • Stories: 1 • Sprinklered: Yes • Protection Class: 4

Location 8: Corporate Headquarters
Address: 401 Congress Avenue, Suite 2800, Austin, TX 78701
Construction: Fire Resistive • Year Built: 2008 • Stories: 1 • Sprinklered: Yes • Protection Class: 5

PROPERTY INFORMATION

Insured
Hill Country Hospitality Partners, LLC

Policy Number
CP-HCHP-2025-3352

Address
604 Brazos Street, Austin, TX 78701

ROOFING

Roof Type
TPO

Roof Age
16 years

Condition Rating
Severe

Estimated Remaining Useful Life
0 years

ROOF CONDITION RATING

Overall Roof Condition: **Excellent**
Estimated Remaining Useful Life: 7 years

ROOF COMPONENTS ASSESSMENT

- Decking: **Poor**
- Flashings: **Good**
- Penetrations: **Good**
- Drainage: **Adequate**
- Parapet Walls: **Cracking**

Need docs

DEFICIENCIES

1. [Code] Multiple areas of ponding water observed on flat roof sections

WIND MITIGATION FEATURES

Roof Deck Attachment
B - Nails (6" o.c.)

Roof-to-Wall Connection
Single Wraps

Roof Geometry
Gable

Secondary Water Resistance
No

Opening Protection
Impact-Rated

RECOMMENDATIONS

#	Priority	Condition Found	Recommended Action	Time Frame
1	Severe	Visible roof deck sagging and water damage indicating potential structural compromise	Engage structural engineer for immediate assessment; restrict access to affected areas pending evaluation	5 days
2	Necessary	Electrical panel clearance obstructed by stored materials	Maintain minimum 36-inch clearance in front of all electrical panels per NEC Article 110.26	30 days
3	Necessary	Hood suppression system in kitchen area has expired	Schedule annual inspection of kitchen hood suppression system per NFPA 96 Section 12.2	30 days
4	Advisable	Exterior lighting inadequate in parking area and loading dock	Install additional lighting to maintain minimum 1 foot-candle at ground level in all exterior areas	60 days
5	Advisable	HVAC rooftop units show signs of deferred maintenance	Establish quarterly preventive maintenance program for all mechanical equipment	90 days
6	Advisable	Hot work permit program not formally documented	Implement written hot work permit program per NFPA 51B; train all affected personnel	60 days

PHOTOGRAPHIC DOCUMENTATION

Photo 1: Rear of building [Image Reference: IMG-4929]

Photo 2: Front of building — street view [Image Reference: IMG-8104]

Photo 3: Storage area — housekeeping conditions [Image Reference: IMG-8696]

Photo 4: Roof condition (aerial or ladder view) [Image Reference: IMG-3385]

Verify

8.16.2025

K. Wilson