FIRE PROTECTION SYSTEM INSPECTION REPORT

Prepared for: Keystone Commercial Builders, Inc.

Inspection Date: 01/30/2026

Report Date: 03/15/2026

Insured Keystone Commercial Builders, Inc.	Policy Number CP-KCB-2025-5583
Address 300 Liberty Avenue, Suite 1200	City, State, ZIP Pittsburgh, PA 15222
SIC Code 1521	Inspector S. Martinez, PE

Check #s

OVERALL RISK GRADE: 3 - Average

Grading Scale: Best's Hazard Index

LOCATIONS INSPECTED

Location 1: Corporate Headquarters
Address: 300 Liberty Avenue, Suite 1200, Pittsburgh, PA 15222
Construction: Fire Resistive • Year Built: 2002 • Stories: 1 • Sprinklered: Yes • Protection Class: 5

Location 2: Main Equipment Yard & Warehouse
Address: 4500 Butler Street, Pittsburgh, PA 15201
Construction: Non-Combustible • Year Built: 1995 • Stories: 1 • Sprinklered: Yes • Protection Class: 3

Location 3: Fabrication Shop
Address: 4520 Butler Street, Pittsburgh, PA 15201
Construction: Masonry Non-Combustible • Year Built: 1988 • Stories: 1 • Sprinklered: Yes • Protection Class: 1

Location 4: South Hills Branch Office
Address: 3000 Village Run Road, Wexford, PA 15090
Construction: Masonry Non-Combustible • Year Built: 2010 • Stories: 2 • Sprinklered: Yes • Protection Class: 4

Location 5: Equipment Storage - Cranberry
Address: 100 Dutilh Road, Cranberry Township, PA 16066
Construction: Non-Combustible • Year Built: 2005 • Stories: 1 • Sprinklered: No • Protection Class: 1

SYSTEM INFORMATION

6/28/2025

System Type Wet Pipe	System Age 28 years K. Wilson
Manufacturer Viking	NFPA 13 Compliant Yes

CONTROL VALVES

3 control valves inspected. All found in open position.
Tamper switches: Connected to monitoring

ALARM DEVICES

Water flow alarm: Tested — operational
Supervisory signal: Deficiency noted

SPRINKLER HEADS

Visual condition: Fair — minor corrosion observed
Spare heads in cabinet: Yes — adequate supply

WATER SUPPLY

Static Pressure 89 psi	Residual Pressure 59 psi
Flow (GPM) 1923	Supply Adequate Yes

DEFICIENCIES

1. [Advisory] Electrical panel clearance obstructed by stored materials
2. [Priority] Exposed wiring and missing junction box covers in main electrical room

SYSTEM STATUS DETERMINATION

Overall System Status: **PASS**