





tips at 16 deg: place carefully




tips at 16 deg: place carefully



tips at 16 deg: place carefully




tips at 16 deg: place carefully



tips at 16 deg: place carefully



tips at 16 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-11.25, 21.25] cm, y [-8.75, 23.75] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")