







tips at 18 deg: place carefully







tips at 18 deg: place carefully



move robot: +x -> assembly spot: -y
board x [-20.70, -0.70] cm, y [-21.85, 6.85] cm
blue: on the board (dashed: support area, dots: contact corners)

10 cm (print at 100%, no "fit to page")