
Three belt conveyors control





Belts 1 & 2 can be started and stopped by pushbuttons. Belt status is displayed by means of respectiv lamp.

Belts 1 & 2 are not allowed to run at the same time. Belt guards monitor belt motion.

After power on, there should be 3 sec delay in guard monitoring of all belts.

When stop button is pressed, the belts 1 and 2 should switch off with delay of 3 sec. and belt three with delay of 6 sec.

If during the running any belt guard from belt 1 or 2 is broken (signal=False), the respective belt motor should be deenergized immediately, but belt three should dwitch off with delay of 6 sec.

The lamps of belt 1 & 2 show failure as flashing.

