```
00C7
                         ; Call Test String to check for Linking
        01
  C8
        2F
                         ;Label
  C9
        8D
             GLO
                   RD
                         RD.0 points to byte after string
  CA.
        A3
             PLO
                   R3
                         ; Putting in R3.0 will cause a skip next N bytes
  CB
             "T,"
        4C
             n T n
  CC
        49
                          Data
  CD
        4E
             44 M 44
             nKn
  CE
        4B
             88 B
  CF
        20
                         (space) (Routine test for 5 bytes)
00D0
        8E
             GLO
                   RE
                         :Test the equality flag (RE.O)
  D1
        3A
             BNZ
                         ; Branch if ≠ 00to Search Table-(String not a
  D2
        D8
                                                                   linker)
        D4
  D3
             SEP
                   R4
  D4
        03
                         ;Else call Set Link Address (RD points to address)
  D5
D6
        CE
                         ;Setting up conditions for inserting address
        30
             BN
                         ; Branch to Insert Address, skipping the label
  D7
        DB
                         ;Search
  DS
        D4
             SEP
                   R4
  D9
        01
                         ; Call Search Symbol Table
        14
  DA
                         (RD points to address)
  DB
        D4
                   R4
             SEP
  DC
        01
                         ; Call Insert Address (R9 points to same
        47
  DD
                                                    Object Code slot)
  DE
        19
             INC
                   R9
        19
                   R9
  DF
             INC
                         ;R9 + 2 =Next Object Code slot
        99
00E0
             GHI
                   R9
                         ;Begin Carriage Return & continue
        FD
  E1
             XRI
                         ;Test if R9 went past end of 3-page
  E2
        0F
                         Object Code Memory area
  E3
        3A
             BNZ
                         ; If not, continue
  E4
        EB
  至5
回6
        F8
             LDI
                         ;Else load error #2-Memory Overflow
        02
  E7
        AE
             PLO
                   RE
                         ;Into RE.O
  E8
        D4
             SEP
                   R4
  E9
        02
                         And Call Error Message halting program
  EA
        B<sub>0</sub>
        D4
  EB
             SEP
                   R4
  EC
        02
                         ; Call Carriage Return
        5F
  ED
  EE
        9\Lambda
             GHI
                   RA
        FB
  EF
             XRI
00F0
        OA
                         :Test if RA.1 = OA = Past page #6
  F1
        3A
             BHZ
  F2
        9B
                         ; If not, continue with 2nd pass
                   R4
  F3
        D4
             SEP
  F4
                         :Else call Set Link Table Back
        03
  F5
F6
        DS
                         ; To prepare for next section
                         ;Branch to Signal User-"Ready" for end
        30
             BM
  F7
        84
                         ; Or next section
```