

Reporting Overview

powered by **sospes**
SAFER WORK | BETTER LIFE

Dark Mode ☐


Total Number Of Reports
413

Total Cost Of Reports
\$0


Start Date
All values

End Date


Report Type




Covered by Workers Comp




Reporting Trends




Report Classification




Business Unit



Facility



Location



Summary Description

75330	Man Gate secured with padlock, but gaps are large enough that someone could shimmy through.
77299	When I got to the site today, I found one of our contractors working very safely. They were on a ladder and had someone holding the ladder, while also tying off to prevent falling. Well done!
79365	When I walked out of Nva01 today, I found the rubber mat near the front door with a ripple in it. It was a very windy day, and the wind had blown it over. I straightened the mat out to prevent it from being a tripping hazard.
79782	Great reception by Security for the summit meetings at NVA this week. Very professional and friendly.
79958	On March 17, 2023, at approximately 1:29 pm, a client's vendor was leaving the building and slipped and fell on the steps in front of NVA01. She reported to NVA01 Security Lead that she just slipped and fell. The Security Lead asked if she needed medical attention, ...
81837	A conduit wire is hanging eye level. It should be attached to the equipment it is suppose to support. Currently it is taped against the wall.
82397	Use of a drone to conduct visual inspections of equipment or structure at heights would mitigate risk of falls or other associated injuries.
82403	green wire from data hall left hanging out of cable tray that could get caught on something or someone.
85883	The new black top at NVA02D does not have "EV parking only" on the spots for EVs. There was a non electric vehicle parked preventing the use of the charger by personnel.
86553	The client was rolling racks across the expansion joint on the second floor near the freight elevator and the aluminum transition was observed to buckle/deform under the constant strain of use. Request an engineering assessment of the aluminum transition piece.

