

1 insert gm card into **card slot** of Tech2



2 Connect self-test adapter with Tech2, then power on machine




3 Enter Main menu then choose F4: tool options

EMAIL: chinauobd2@gmail.com

Skype: UOBD2.COM MSN: sales@uobd2.com

Yahoo: UOBD2COM@yahoo.cn





4 Choose F3: SELF-TEST



5 Press "Exist" to continue

EMAIL: chinauobd2@gmail.com

Skype: UOBD2.COM MSN: sales@uobd2.com Yahoo: UOBD2COM@yahoo.cn



1. CANdi must not be conr 2. ALDL loopback should to connected (GM3000109). 3. Failure to follow these instructions may invalid the self test. Press [EXIT] to continue

6 Choose Tech 2 self-test

	Tech 2 Self Test Version 6.40
0:	Automated Main PCB and V
1:	Automated Main PCB
2: 1	Automated VCI +
3: (Selectable Main PCB
4: 5	Selectable VCI
5: I	Power On Self Test Resul
6: I	Hardware ID

7 Automated VCI

EMAIL: chinauobd2@gmail.com

Skype: UOBD2.COM MSN: sales@uobd2.com Yahoo: UOBD2COM@yahoo.cn



	Tech 2 Self Test Version 6.40
	Automated Main PCB and VI Automated Main PCB Automated VCI
F4: F5:	Selectable Main PCB Selectable VCI Power On Self Test Resul- Hardware ID

8 VCI self-test result

Tuesday Februa	ry 23 2011 04:57
Test Complete	
MUXPass SIPO 8Pass DLC 1Pass TPUPass CCDPass J1708Pass	ADCPass SIPO 20Pass DLC 2Pass HBCCIGNORED Dual Uart.Pass Gnd FETPass
Level Shifters Cross Point Short L and M Test I/O1-I/O16 LoopBack	PassPassPassPass

EMAIL: chinauobd2@gmail.com

Skype: UOBD2.COM
MSN: sales@uobd2.com

Yahoo: UOBD2COM@yahoo.cn