

IT INCIDENT REPORT SAMPLE

Incident Type: Laptop Touchpad Failure in Mini Windows Environment
Prepared Date: 23 May 2026

Field	Details
Incident ID	INC-2026-001
Reported By	IT Support Technician
Department	Technical Support
Affected Device	Windows Laptop
Issue Severity	Medium
Status	Resolved
Date Reported	23/05/2026

Incident Summary

A user reported that the laptop touchpad stopped functioning after installing a modified Mini Windows operating system. The touchpad became unresponsive, making navigation difficult without an external mouse.

Root Cause Analysis

Investigation revealed that the Mini Windows installation removed or disabled important touchpad drivers and HID services required for the laptop hardware to function correctly.

Troubleshooting Steps

1. Connected an external USB mouse.
2. Checked Device Manager for missing drivers.
3. Enabled touchpad using keyboard shortcuts.
4. Installed official touchpad drivers.
5. Enabled Internal Pointing Device in BIOS.
6. Ran Windows Updates.
7. Restarted and tested functionality.

Resolution

The issue was successfully resolved after installing official drivers and enabling the touchpad in BIOS settings. The laptop touchpad resumed normal operation.

Recommendations

- Avoid heavily modified Windows builds.
- Keep official drivers available.
- Enable Windows Update services.
- Create restore points before major system changes.

Reference Image

