

[illegible]

Servo Ports

The diagram illustrates the wiring for two servo ports, J10 and J9, on a Raspberry Pi. Each port is connected to a +5V supply and a ground (GND) connection. The wiring for J10 is as follows: SP2 PWM is connected to pin 1, SP1 PWM is connected to pin 2, +5V is connected to pin 5, and GND is connected to pin 6. The wiring for J9 is as follows: SP4 PWM is connected to pin 1, SP3 PWM is connected to pin 2, +5V is connected to pin 5, and GND is connected to pin 6.

Extras

The 'Extras' section contains two circuit diagrams for the SY8113BADC converter.

3V3 Buck Converter (U7): This circuit converts a 5V input to 3.3V. It features a 10uF, 25V input capacitor (C26), a 4.7uH inductor (L3), and a 100nF output capacitor (C27). The feedback network consists of a 10kΩ resistor (R10) and a 15kΩ resistor (R12). The output is connected to a 3.3V LED (D2 Green) through a 1kΩ resistor (R2).

5V Buck Converter (U6): This circuit converts a 5V input to 5V. It features a 10uF, 25V input capacitor (C20), a 4.7uH inductor (L2), and a 100nF output capacitor (C21). The feedback network consists of a 36kΩ resistor (R9) and a 4k7Ω resistor (R11). The output is connected to a 5V LED (D3 Green) through a 1kΩ resistor (R2).

Rev:
Id: 1/1

