

Daniel Healy - 0423 736 921 Dean Willits - 0411 108 047

info@arwc.com.au

QBCC: 15207741 NSW: 378147C ABN: 79169511693 ACN: 069 511 693

Roof Report

Job Number:	
Site Address:	
Supervisor:	
Client:	

AX1057-CF884 AAARW Roof Report Cyclone Alfred NEW

Insured's Reported Damage	
Summary of the reported damage?	
Claimed Date Of Event?	Wednesday, 14th May, 2025
Any prior repairs or interventions?	No
Attendance Date	Tuesday, 5th Aug, 2025
Attendance Time	11:30 am
Weather at Time of Inspection	Sunny/fine
Light Conditions	Bright & Sunny
Property Overview	
Will power need to be isolated to access the roof cavity?	Yes
Has the power been isolated to access the cavity?	
Property Type	House
Age of Property	21-50 Years
General Property Condition	Average
Construction Type	Weatherboard
Construction Type Roof Type	Weatherboard Asbestos
Roof Type	Asbestos
Roof Type Roof Condition	Asbestos Fair
Roof Type Roof Condition Roof Age Roof Pitch	Asbestos Fair 21-50 Years
Roof Type Roof Condition Roof Age	Asbestos Fair 21-50 Years





Daniel Healy - 0423 736 921 Dean Willits - 0411 108 047 info@arwc.com.au

QBCC: 15207741 NSW: 378147C ABN: 79169511693 ACN: 069 511 693

Was an inspection to the ceiling cavity conducted	NA - Due to safety issues
Does the distance between truss spacings exceed 600mm? (photos required)	NA - This is a hand pitch roof/ metal roof structure
Type of battens present?	Timber
Type of Membrane Present?	None Visible
Does the roof comply with current standards	No
Does the roof comply to manufacturers standards?	No - But at the time of installation it would have
Are there any Roof Maintenance issues? Please Specify.	Gutter filled with debris. Nails dislodged from roof sheets
Have you informed the insured of maintenance?	No
What percentage of the roof is damaged	
What Damages is present on the roof from visual inspection	Tree Impact
Is the roof damage related to an insured event	Yes
Is there gutter guard present	Yes
Are spreader down pipes installed correctly (position of drain to valleys of sheets or tile laps)	Yes
Are all flashings installed correctly, including dektites and lead flashings, and are flashings in good condition/performing correctly	Yes
Are the gutters clean and clear of debris including valley gutters, box gutter spitters and standard guttering?	Yes
Has the roof been affected by wind lift	No
If Yes, is this due to event related damage or for certification purposes	
Has the event caused the materials life span to decrease?	No - in our opinion from a visual aspect, the event has not affected the life span to decreasee
Is the roof requiring full replacement	Yes



QBCC: 15207741 NSW: 378147C ABN: 79169511693 ACN: 069 511 693

Has the structural integrity of the Yes roof scoped for been reduced as a direct result of the event? **Roof Inspection Findings** Tree branch had fallen onto roof and smashed 1 solar panel. Roof is leaking directly below this area however cannot be fully viewed without removing solar Internal Damage Assessment **Rooms Inspected** Lounge Type of damage claimed Mould, Water Igress **Sustained Resulting Damages** Mould, Staining Condition Of Existing Ceiling & Fair Walls **Internal Inspection** Water staining in front lounegroom ceiling **Maintenance Internal** Maintenance Findings **Maintenance Summary** Conclusion Conclusion Repair & Remedial Action Plan **Insurance Repairs** Solar panel replacement and roof sheet replacement. (Due to asbestos, full roof will require replacement **Additional Repairs & Maintenance** none

Report Images



ARW Construction 46 Azure Way, Coomera Qld 4209

Daniel Healy - 0423 736 921 Dean Willits - 0411 108 047 info@arwc.com.au

QBCC: 15207741 NSW: 378147C ABN: 79169511693 ACN: 069 511 693

Report Photos