

- 2. Material: Stainless Steel
- 3. Part must be free of sharp edges and debris
- 4. Lead screw must be consistently smooth and not contain pits or gouges

