



Calibration: laser offset from the mount design; laser angle from any rigid object shot near and far (apparent-size constancy), no labels.