


# Implied yaw floor before and after the August repair

● Borrowed calibration    ◆ After  $\varphi$  repair

Dive 60  $\leftarrow$  65     $\varphi = -0.1458^\circ$



Dive 76  $\leftarrow$  63     $\varphi = -0.1505^\circ$

