



What limits “exact by construction” is assembly, not specification

A constant we only think we know



How well it is built



Misspecifying the chamfer by ± 0.15 mm moves f_x by less than the estimator's own scatter. Assembly slop does bind — about 1 % of length at 0.2 mm — and it leaves the f_x/f_y ratio, the quantity the tower is for, alone.