Fabricated and mounted a new throttle



Steering column and kingpins were bored out so we welded machine bushings to fix the problem