

SAJAG Safety Observation Report

Report ID: TEST-PDF-001

Date: 28 August 2026

Site: Plant A

Activity: Scaffold Material Shifting

Safety Observation

During scaffold material shifting, a worker leaned beyond the guardrail without fall protection while a suspended load moved overhead.

Observed Risk Factors

The observation indicates potential fall exposure, work near a suspended load, and failure to use appropriate fall protection controls.

Purpose

This text-based PDF is created specifically to test the SAJAG PDF analysis endpoint. It should be uploaded through the Analyze PDF Report feature.

Field	Value
Report ID	TEST-PDF-001
Site	Plant A
Activity	Scaffold Material Shifting
Report Type	Safety Observation