

MANGALORE REFINERY AND PETROCHEMICALS LTD (MRPL)

FIELD INSPECTION REPORT - UNIT 42

DATE: 2026-09-01

INSPECTOR: R. KUMAR

FINDING 1: Corrosion observed on primary inlet valve V-102. Depth approx 2mm.

FINDING 2: Secondary containment bund wall shows minor hairline cracks near sector 4.

FINDING 3: Flow meter FT-205 display erratic. Suspect loose wiring.

FINDING 4: Seal on pump P-101B weeping slightly. Needs monitoring.

FINDING 5: Thermal insulation missing on a 2-meter section of high-pressure steam line L-88.

*Handwritten Note: Pressure drop across
V-102 seems excessive. Check sensor data!*