

MANGALORE REFINERY AND PETROCHEMICALS LTD (MRPL)

FIELD INSPECTION REPORT - UNIT 42

DATE: 2026-09-01 | INSPECTOR: R. KUMAR (ID: MRPL-INS-884)

FINDING 1: Corrosion observed on primary inlet valve V-102. Depth approx 2mm. Localized pitting near flange collar.

FINDING 2: Secondary containment bund wall shows minor hairline cracks near sector 4. Integrity uncompromised.

FINDING 3: Flow meter FT-205 display erratic. Suspect loose wiring at junction box JB-205.

FINDING 4: Seal on pump P-101B weeping slightly. Needs monitoring during next operational cycle.

FINDING 5: Thermal insulation missing on a 2-meter section of high-pressure steam line L-88. Heat loss detected.

INSPECTOR HANDWRITTEN REMARKS / ACTION ITEMS:

Handwritten Note: Pressure drop across V-102 seems excessive.  
Correlate w/ flow rate data from FT-205. Check sensor readings immediately!  
Signed: R. Kumar 2026-09-01