Sharp X1 Twin Main Board

| Designation | Brand | Model | Markings 1 | Markings 2 | Notes |
|-------------|--------|----------------|-------------|------------|----------|
| | | | | | |
| IC1 | YAMAHA | YM2149F | 9024 GADG | | |
| IC2 | SHARP | Z80A-CPU-D | LH0080A | 28ZDB | |
| IC3 | TI | SN74LS541N | K 041X S07 | | |
| IC4 | TI | SN74LS541N | K 041X S07 | | |
| IC5 | TI | SN74LS541N | K 041X S07 | | |
| IC6 | TI | SN74LS541N | K 041X S07 | | |
| IC7 | NEC | D4990AC | 9044S7 | | |
| IC8 | SHARP | M80C49-277 | 8E | 0Z004 | |
| IC9 | SHARP | IX1031CE | 9034 W02 | | |
| IC10 | F? | MB4107A | 9049 M09 | | |
| IC11 | NEC | D8255AC-2 | 9045XD013 | | |
| IC12 | F? | MB8877A | 9048 Z68 | | |
| IC13 | NEC | D8255AC-2 | 9045XD013 | | |
| IC14 | TI | SN74LS07N | 045XS | | |
| IC15 | TI | SN74LS07N | J027XJK | | |
| IC16 | F? | MB89321B | 9044 Z11 | | |
| IC17 | | NMC27C32BQ | LB9024 | 200 | IX1742CE |
| IC18 | F? | MB81464-12 | 9050 T08 BB | | |
| IC19 | F? | MB81464-12 | 9050 T08 BB | | |
| IC20 | TI | SN74LS24SN | K 040B S92 | | |
| IC21 | TI | SN74LS24SN | K 040B S92 | | |
| IC22 | | BA7021 | 104 395 | | |
| IC23 | TI | SN74LS04N | J037 AJ92 | | |
| IC24 | SHARP | IX1033CE | F08 327 | | |
| IC25 | F? | MB8416A-15L-SK | 9035 R88 | | |
| IC26 | F? | MB8416A-15L-SK | 9035 R88 | | |
| IC27 | SHARP | X1034CE | 9044 B | | |
| IC28 | SHARP | IX1035CE | 9031 W02 | | |
| IC29 | SHARP | IX1032CE | F05 261 | | |
| IC30 | SHARP | X0830CE | 9029 D | | |
| IC31 | | BA7230LS | 102 333 | | |
| IC32 | F? | MB81416-10 | 8939 T89 | | |
| IC33 | F? | MB81416-10 | 8939 T89 | | |

Sharp X1 Twin Main Board

| IC34 | F? | MB81416-10 | 8939 T89 | | |
|----------|----|----------------|-----------|-----|----------|
| IC35 | F? | MB81416-10 | 8939 T89 | | |
| IC36 | F? | MB81416-10 | 8939 T89 | | |
| IC37 | F? | MB81416-10 | 8939 T89 | | |
| IC38 | F? | MB8416A-15L-SK | 9035 R88 | | |
| IC39 | F? | MB8416A-15L-SK | 9035 R88 | | |
| IC40 | F? | MB8416A-15L-SK | 9035 R88 | | |
| IC41 | | NMC27C32BQ | LB9024 | 200 | IX1743CE |
| IC42 | TI | SN74LS14N | 044AS | | |
| IC43 | TI | SN74LS541N | 041X 507 | | |
| IC44 | TI | SN74LS14N | 044AS | | |
| IC45 | TI | SN74LS06N | 031AJ | | |
| IC47 | | BA526 | 104 392 C | | |
| | | | | | |
| NO IC46? | | | | | |

Sharp X1 Twin PCE Board

| Designation | Brand | Model | Markings 1 | Markings 2 | Notes |
|----------------|--------|---------------|------------|------------|-------|
| | | | | | |
| IC401 | | HSRM2264LM10 | F01F 217 | | |
| IC402 (Bottom) | HUDSON | HUC6280 | F07D 315 | | |
| IC403 (Bottom) | | HSRM20256LM12 | F04H 204 | | |
| IC404 (Bottom) | | HSRM20256LM12 | F04H 204 | | |
| IC405 (Bottom) | HUDSON | HUC6260 | F09 637 | | |
| IC406 (Bottom) | HUDSON | HUC6270 | F01 527 | | |

Sharp X1 Twin

PCE Interface Board

| Designation | Brand | Model | Markings 1 | Markings 2 | Notes |
|-------------|-------|---------|------------|------------|-------|
| | | | | | |
| IC201 | | BA10324 | 048 408 | | |

Sharp X1 Twin

Power Supply

| Designation | Brand | Model | Markings 1 | Markings 2 | Notes |
|-------------|-------|-------|------------|------------|-------|
| | | | | | |