

		FIR	
Product Code	DL548	Centralised ID	DTIL25030033
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	25-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030033	
2	Date of communication failure	2024-11-12 17:18:00	
3	Device Model	DL548	
4	Defective device PSN	2403047152	
5	VIN Number	MB1NEVHD0RRKW5062	
6	Device IMEI	867409070547174	
7	Device CCID	8.991643093472969e+19	
8	Date of Sale of Device	12-03-2024	
9	S Trigger Date	21-05-2024	
10	C Trigger Date	12-07-2024	
11	Commercial Expiry date	11-07-2024	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	Haulage	
14	Failure Location Plant/ Field- Customer Address	ASSAM	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Arun Maity	
18	Reason for Replacement/Repair	Repair	
19	Dealer Location	New Rajdhani Motors, ■ Tamulikuchi, 13th mile, jorabat, Guwahati, 782402	
20	Darby Last communication date	2024-11-12 17:18:00	
21	Device Replacement request Initiation date	2025-03-25 12:22:27	
22	Returnable / Non-Returnable	Repair	
Approved By:		Name	Date
Initiated by- Service Eng.		Arun Maity	25-03-2025
Service Manager		Eliyas	.
Sales & Service Head		Rajendran Subramanian	.