

		FIR	
Product Code	DL548	Centralised ID	DTIL25030037
Customer	A.L	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	26-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030037	
2	Date of communication failure	2025-01-02 05:39:00	
3	Device Model	DL548	
4	Defective device PSN	2408057125	
5	VIN Number	MB1H3LHD9RRGZ4937	
6	Device IMEI	867950076206703	
7	Device CCID	8.991643124482294e+19	
8	Date of Sale of Device	19-08-2024	
9	S Trigger Date	04-09-2024	
10	C Trigger Date	30-10-2024	
11	Commercial Expiry date	29-10-2025	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	RMC	
14	Failure Location Plant/ Field- Customer Address	BHAKROTA-JAIPUR	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Arun Maity	
18	Reason for Replacement/Repair	Not Powering ON	
19	Dealer Location		
20	Darby Last communication date	2025-01-02 05:39:00	
21	Device Replacement request Initiation date	2025-03-26 12:15:58	
22	Returnable / Non-Returnable	Repair	
Approved By:		Name	Signature
Initiated by- Service Eng.		Arun Maity	Arun Maity
Service Manager		Kunal	.
Sales & Service Head		Rajendran Subramanian	.