

		FIR	
Product Code	DL548	Centralised ID	DTIL25030027
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	21-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030027	
2	Date of communication failure	N/A	
3	Device Model	DL548	
4	Defective device PSN	2502257003	
5	VIN Number	MB1NECHD6SRNE9916	
6	Device IMEI	861409078590131	
7	Device CCID	916441244829288000	
8	Date of Sale of Device	26-02-2025	
9	S Trigger Date	N/A	
10	C Trigger Date	N/A	
11	Commercial Expiry date	N/A	
12	Active Profile (BSNL/Airtel/Dual)	BSNL	
13	Vehicle Type / Model	N/A	
14	Failure Location Plant/ Field- Customer Address	INSIDE AL HOSUR PLANT	
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Eliyas	
18	Reason for Replacement/Repair	Repair	
19	Darby Last communication date	N/A	
20	Device Replacement request Initiation date	2025-03-21 13:46:30	
21	Returnable / Non-Returnable	Repair	
Approved By:		Name	Date
Initiated by- Service Eng.		Eliyas	21-03-2025
Service Manager		upendram	N/A
Sales & Service Head		Rajendran Subramanian	N/A

