ARGUS_METADATA: {"doc_date":"2024-11-18","version":"v1","document_id":"NSI-INC-2024-006","doc_type":"incident_report","confidentiality":"internal","status":"historical","product":"Meridian Sensor","supplier":"Or

MOCK INTERNAL DOCUMENT - HISTORICAL SUPPLY INCIDENT REPORT.

In 2024, a packaging delay from Oriole Packaging interrupted Meridian Sensor final assembly for nine days.

A two-week buffer inventory and a temporary qualified alternate package reduced customer impact.

The incident review recommends confirming current inventory and alternate qualification rather than assuming historical mitigations remain available.