



3630 Chatwood Dr Pearland Texas 77584

COURTESY OF

Sent: Sat, 06 May 2023 23:30

PREPARED BY:

Repair Pricer Team

QUESTIONS?
CLICK HERE TO GET HELP



ltem	Pg	Action	Range Price
MACON			
	11	Renair and natch mortar and brick as needed	\$609 - \$859
		Repair and pater mortal and brick as needed	φουσ φουσ
	12	Remove brick and install lintel at openings then reinstall brick	\$802 - \$1120
		Sub-Total (Mason)	\$1411 - \$1979
HANDYMAN			
Wood rot observed on areas of house/garage. Garage 26 frame, back door.	10	Replace or repair damaged areas noted and seal to extend life of materials	\$1080 - \$1470
Damage to the siding observed	11	Repair noted areas and seal to extend life of materials	\$710 - \$982
Freeze board separation at one or more corners of the house. Indication of foundation movement.	11	Secure damaged frieze board and seal	\$291 - \$357
Missing or non-functioning door stop behind one or more doors to prevent damage to sheetrock	13	Install in noted locations to prevent damage on walls	\$125 - \$153
			\$220 - \$274
	r13		\$314 - \$392
penetration from damaging interior building components. High-risk areas include exterior doors with little to no roof or balcony overhang protection from the elements.		materials	
The exterior door does not have a thumb latch to unlock the door. All egress doors shall be opened from the inside without the use of a key or special knowledge or effort. Ref. IRC R311.2.	a13	Replace with a latch interior deadbolt to improve safety	\$168 - \$212
Observed water damage under one or more sink from a previous water leak. No leaks were detected at the time of inspection. (Guest bathroom).	:21	Paint and repair damaged areas	\$350 - \$442
		Sub-Total (Handyman)	\$3258 - \$4282
ELECTRICIAN			
Ceiling fan found to be not functioning, master bedroom	16	Service ceiling fans	\$121 - \$151
	16	Repair or install outlet, switch covers and secure throughout	\$122 - \$152
		Sub-Total (Electrician)	\$243 - \$303
DDVWALL/DAINTED			
	10	Patch areas of sheetrock and paint areas noted throughout	\$427 - \$589
Countries oracle and of proviously repaired oracles in the shoelfook observed over somethially doors, willidows, and/or comes	10	including loose tape	ψ21 - ψ009
		-	
Caulking missing and/or deficient around windows / vertical trim / joints in siding. May allow wind driven rain entry.	11	Correctly seal noted windows to extend life of frame	\$366 - \$450
	Cracks in brick veneer and/or repairs, one or more locations, Recommend buyer take photographs of cracks, their location, and width [ruler across the crack] with a high- resolution camera that has a date stamp for future reference Comments: ceiling: sags in the ceiling were observed near kitchen entrance HANDYMAN Wood rot observed on areas of house/garage. Garage 26 frame, back door. Damage to the siding observed Freeze board separation at one or more corners of the house. Indication of foundation movement. Missing or non-functioning door stop behind one or more doors to prevent damage to sheetrock Door damaged, guest bedroom front door Did not observe door pan flashing at exterior door location(s). Properly installed door pan flashing helps prevent wind-driven rain/wate penetration from damaging interior building components. High-risk areas include exterior doors with little to no roof or balcony overhang protection from the elements. The exterior door does not have a thumb latch to unlock the door. All egress doors shall be opened from the inside without the use of a key or special knowledge or effort. Ref. IRC R311. 2. Observed water damage under one or more sink from a previous water leak. No leaks were detected at the time of inspection. (Guest bathroom).	Cracks in brick veneer and/or repairs, one or more locations, Recommend buyer take photographs of cracks, their location, and width 11 [ruler across the crack] with a high- resolution camera that has a date stamp for future reference Comments: ceiling: sags in the ceiling were observed near kitchen entrance 12 HANDYMAN Wood rot observed on areas of house/garage. Garage 26 frame, back door. 10 Damage to the siding observed 11 Freeze board separation at one or more corners of the house. Indication of foundation movement. 11 Missing or non-functioning door stop behind one or more doors to prevent damage to sheetrock 13 Door damaged, guest bedroom front door 13 Did not observe door pan flashing at exterior door location(s). Properly installed door pan flashing helps prevent wind-driven rain/water13 penetration from damaging interior building components. High-risk areas include exterior doors with little to no roof or balcony overhang protection from the elements. The exterior door does not have a thumb latch to unlock the door. All egress doors shall be opened from the inside without the use of at3 key or special knowledge or effort. Ref. IRC R311. 2. Observed water damage under one or more sink from a previous water leak. No leaks were detected at the time of inspection. (Guest 21 bathroom). ELECTRICIAN Celling fan found to be not functioning, master bedroom 16 One or more cover plates were either missing or damaged in attic 16	MASON Cracks in brick veneer and/or repairs, one or more locations, Recommend buyer take photographs of cracks, their location, and width 11 [ruler across the crack] with a high- resolution camera that has a date stamp for future reference Comments : ceiling: sags in the ceiling were observed near kitchen entrance **Sub-Total (Mason)** **ANDYMAN** Wood rot observed on areas of house/garage. Garage 26 frame, back door. Damage to the siding observed **Damage to the siding observed observed in the observed observed observed observed observed observed obs



#	ltem	Pg	Action	Range Price
16	Nail-heads were observed to be pushing through the interior finish in one or more locations of the home	12	Price Included In Item 13. (Patch areas of sheetrock and paint	
			areas noted throughout including loose tape.).	
17	Water supply plumbing: recommend insulating exterior water lines to prevent freeze damage	20	Seal penetration noted	\$112 - \$142

			Sub-Total (DryWall/Painter)	\$905 - \$1181
	PLUMBER			
18	Corrosion noted at water shut off valves below one or more sinks	21	Repair corroded shut offs or replace	\$159 - \$203
19	Hot/cold reversed, Hot water supply to any fixture shall be installed on the left side, Standard Plumbing Code both faucet in the master		·	\$112 - \$138
	bathroom shower, kitchen faucet		· ·	
20	One or more drain stoppers do not operate properly, needs adjustment	22	Install or repair drain stoppers in areas as needed	\$114 - \$146
21			Install anti-siphon or vacuum breaks on exterior hose bibs	\$149 - \$197
			Sub-Total (Plumber)	\$534 - \$684
	HVAC CONTRACTOR			
22	Improperly located, thermostats are supposed to be located near the return air chase	18	Relocate to improve efficiency	\$375 - \$475
			Sub-Total (HVAC Contractor)	\$375 - \$475
	DECK/FENCING CONTRACTOR			
23	Fence is in poor condition. Notably east side of the house.	6	Repair as needed in noted areas	\$406 - \$502
			Sub-Total (Deck/Fencing Contractor)	\$406 - \$502
	DOOFING CONTRACTOR			
24	ROOFING CONTRACTOR	0	Denois load flocking and use correct vall down technique	\$204 \$250
24	Not all lead flashing of drain waste vents are properly rolled down the interior of plumbing vent pipes and/or are damaged by squirrels,	0	Repair lead hashing and use correct roll down technique	\$204 - \$250
	which may allow some rainwater entry			
			Sub-Total (Roofing Contractor)	\$204 - \$250
			Sub-Total (Nooling Contractor)	\$20 4 - \$250
	LANDSCAPER			
25	Comments: drainage swale is not continuous at sides the drainage swale must be kept clear and continuously sloped to drain water	6	Extend and clear swales to drain water	\$399 - \$507
	properly	•		1 110 4001
26	Soil grade and drainage patterns around some areas of house do not appear to properly direct water away from foundation to aid in	6	Dig swales into lot to drain water and level out high or low soil	\$568 - \$792
	controlling runoff water and could cause differential movement of the foundation or water penetration during heavy rains		levels	
	5			
1				1



High soil and patio obscures the view of foundation and prevents visual inspection for termite and/or water penetration Sub-Total (Landacaper) Sub-T	#	ltem	Pg	Action	Range Price
WINDOW/GLASS CONTRACTOR 28 Comments: windows: one or more windows will not stay open or will not open fully master bedroom 14 Check and repair windows and replace hardware as needed 29 One or more screens are missing and/or damaged 315 - \$387 30 One or more screens are missing and/or damaged 316 - \$287 317 Safety glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 32 Sately glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 32 Sub-Total (Window/Glass Contractor) 33 Safety glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 33 Safety glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 34 Safety glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 35 Sub-Total (Window/Glass Contractor) 36 Safety glass in hazardous locations and safety glass to improve safety 3706 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3707 - \$966 3	27	High soil and patio obscures the view of foundation and prevents visual inspection for termite and/or water penetration	15	Adjust soil at areas near foundation to extend life of materials	\$424 - \$592
WINDOW/GLASS CONTRACTOR Comments: windows: one or more windows will not stay open or will not open fully master bedroom 14 Check and repair windows and replace hardware as needed 3315 - \$387 29 One or more screens are missing and/or damaged 14 Replace windows were difficult to open 15 Replace windows screens are missing and/or damaged 16 Replace windows screens are missing and/or damaged 17 Replace windows screens are missing and/or damaged 18 Replace with safety glass to improve safety 19 Safety glass in hazardrus locations; large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 18 Safety glass in hazardrus locations; large picture windows so not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 18 Safety glass in hazardrus locations; large picture windows so not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 18 Safety glass in hazardrus locations; large picture windows so not appear to be safety/tempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety 18 Safety glass in hazardrus locations; large picture windows some safety 18 Safety glass in hazardrus locations; large picture windows some safety 18 Safety glass in hazardrus locations; large picture windows some safety 18 Safety glass in hazardrus locations; large picture windows some safety 18 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass in hazardrus locations; large picture safety 19 Safety glass				0.1.7.(1/1)	\$4004 \$4004
Comments : windows: one or more windows will not stay open or will not open fully master bedroom 14 Cheek and repair windows and replace hardware as needed 3315 - \$387 70 no or more windows were difficult to open 30 One or more screens are missing and/or damaged 3329 - \$423 3339 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3341 - \$423 3441 - \$42				Sub-Total (Landscaper)	\$1391 - \$1891
One or more windows were difficult to open 14 Service call to adjust noted windows and repair noted items 383 - \$453 30 One or more screens are missing and/or damaged 31 Replace windows occess are missing and/or damaged 32 Sately glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety/th 36 of traffic area. Sub-Total (Window/Glass Contractor) \$2313 - \$3085 FIREPLACE/CHIMNEY CONTRACTOR Metal chimney cap deformed/rusted, improperly holds water instead of shedding water 15 Service and seal to extend life of materials \$223 - \$275 Sub-Total (Fireplace/Chimney Contractor) \$223 - \$275 GARAGE DOOR CONTRACTOR Stickylnoley operation, recommend adjustment and/or lubrication 32 Stickylnoley operation, recommend adjustment and/or lubrication 33 Comments: unit has excessive wibration / noise level recommend lubrication 34 Comments with the sexessive wibration in onese level recommend lubrication 35 Recommend calulking around the base of all commodes 36 Recommend calulking around the base of all commodes 37 Recommend calulking around all tub/shower faucets and spouls to prevent water entry behind the wall 38 PLIANCE CONTRACTOR 39 Comments: Unit noise level recommend substitute the same point of the same point and adjusting an eneeded throughout 38 Sub-Total (Girage Door Contractor) 39 Sub-Total (Girage Door Contra		WINDOW/GLASS CONTRACTOR			
One or more screens are missing and/or damaged Safety glass in hazardous locations: large picture windows do not appear to be safety/rempered glass. Considered a recognized safety/4 Replace with safety glass to improve safety Sub-Total (Window/Glass Contractor) Sub-Total (Fireplace/Chimney Contractor) Sub-Total (Fireplace/Chimney Contractor) Sub-Total (Fireplace/Chimney Contractor) Sub-Total (Fireplace/Chimney Contractor) Sub-Total (Garage Door Contractor) Su	28	Comments : windows: one or more windows will not stay open or will not open fully master bedroom	14	Check and repair windows and replace hardware as needed	\$315 - \$387
Safety glass in hazardous locations: large picture windows do not appear to be safety/tempered glass. Considered a recognized safety14 Replace with safety glass to improve safety \$766 - \$966 hazard. Per ire 308. 4, 7 windows greater than 9 sq. Ft., bottom less than 18 above the floor, top more than 36 above the floor, within \$20	29	One or more windows were difficult to open	14	Service call to adjust noted windows and repair noted items	\$363 - \$453
hazard. Per irc 308. 4. 7 windows greater than 9 sq. Ft. , bottom less than 18 above the floor, top more than 36 above the floor, within 36 of traffic area. Sub-Total (Window/Glass Contractor) \$2313 - \$3085 FIREPLACE/CHIMNEY CONTRACTOR Metal chimney cap deformed/rusted, improperly holds water instead of shedding water \$223 - \$275 Sub-Total (Fireplace/Chimney Contractor) \$223 - \$275 GARAGE DOOR CONTRACTOR 3 Sticky/noisy operation, recommend adjustment and/or lubrication 4 Service call to adjust garage door and repair noted items \$151 - \$189 Comments: unit has excessive vibration / noise level recommend lubrication 5 Service call to install sticker \$15 Service call to adjust garage door and repair noted items \$151 - \$189 \$151 - \$189 \$223 - \$275 GARAGE DOOR CONTRACTOR 3 Sticky/noisy operation, recommend adjustment and/or lubrication 14 Service call to adjust garage door and repair noted items \$151 - \$189 \$151 - \$189 \$25 Service call to install sticker \$111 - \$139 TILE & GROUT CONTRACTOR 3 Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 2 Caulk or grout around commode and shower penetrations \$219 - \$279 \$210 - \$460 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 2 Replace with braided as needed \$121 - \$151 \$25 Install anti-sphon or vacuum break on dishwasher drain line \$91 - \$113	30	One or more screens are missing and/or damaged	14	Replace window screens around property	\$929 - \$1279
FIREPLACE/CHIMNEY CONTRACTOR Metal chimney cap deformed/rusted, improperly holds water instead of shedding water Sub-Total (Fireplace/Chimney Contractor) S223 - \$275 GARAGE DOOR CONTRACTOR Sticky/noisy operation, recommend adjustment and/or lubrication Sticky/noisy operation, recommend adjustment and/or lubrication 14 Service call to adjust garage door and repair noted items \$151 - \$189 Comments: unit has excessive vibration / noise level recommend lubrication 26 Adjust and repair garage door for safe operation \$167 - \$2211 Sub-Total (Garage Door Contractor) \$429 - \$539 TILE & GROUT CONTRACTOR Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 27 Grouting and caulking as needed throughout \$151 - \$189 Sub-Total (Tile & Grout Contractor) \$29 - \$279 Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 28 Replace with braided as needed \$121 - \$151 \$91 - \$113	31	hazard. Per irc 308. 4. 7 windows greater than 9 sq. Ft., bottom less than 18 above the floor, top more than 36 above the floor, within	-	Replace with safety glass to improve safety	\$706 - \$966
32 Metal chimney cap deformed/rusted, improperly holds water instead of shedding water Sub-Total (Fireplace/Chimney Contractor) \$223 - \$275 GARAGE DOOR CONTRACTOR \$33 Sticky/noisy operation, recommend adjustment and/or lubrication Comments: unit has excessive vibration / noise level recommend lubrication Missing required safety sticker/decal next to the operator button \$14 Service call to adjust garage door and repair noted items \$151 - \$189 Comments: unit has excessive vibration / noise level recommend lubrication \$26 Service call to install sticker \$111 - \$139 Sub-Total (Garage Door Contractor) \$429 - \$539 TILE & GROUT CONTRACTOR Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 22 Caulk or grout around commode and shower penetrations \$219 - \$279 Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage \$280 - \$280				Sub-Total (Window/Glass Contractor)	\$2313 - \$3085
32 Metal chimney cap deformed/rusted, improperly holds water instead of shedding water Sub-Total (Fireplace/Chimney Contractor) \$223 - \$275 GARAGE DOOR CONTRACTOR \$33 Sticky/noisy operation, recommend adjustment and/or lubrication Comments: unit has excessive vibration / noise level recommend lubrication Missing required safety sticker/decal next to the operator button \$14 Service call to adjust garage door and repair noted items \$151 - \$189 Comments: unit has excessive vibration / noise level recommend lubrication \$26 Service call to install sticker \$111 - \$139 Sub-Total (Garage Door Contractor) \$429 - \$539 TILE & GROUT CONTRACTOR Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 22 Caulk or grout around commode and shower penetrations \$219 - \$279 Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage \$280 - \$280		FIREPLACE/CHIMNEY CONTRACTOR			
GARAGE DOOR CONTRACTOR 33 Sticky/noisy operation, recommend adjustment and/or lubrication 34 Comments: unit has excessive vibration / noise level recommend lubrication 35 Missing required safety sticker/decal next to the operator button 36 Service call to adjust garage door for safe operation 37 Service call to install sticker 38 Sub-Total (Garage Door Contractor) 38 Recommend caulking around the base of all commodes 39 Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 30 Sub-Total (Tile & Grout Contractor) 31 Sub-Total (Tile & Grout Contractor) 32 Sub-Total (Tile & Grout Contractor) 33 Sub-Total (Tile & Grout Contractor) 34 Service call to adjust garage door and repair noted items 35 APPLIANCE CONTRACTOR 36 Recommend caulking around the base of all commodes 37 Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 38 Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 30 Sib-Total (Tile & Grout Contractor) 31 Sib-Total (Tile & Grout Contractor) 32 Replace with braided as needed 33 Sib-Total (Tile & Grout Contractor) 34 Sib-Total (Tile & Grout Contractor) 35 Sib-Total (Tile & Grout Contractor) 36 Sib-Total (Tile & Grout Contractor) 37 Sib-Total (Tile & Grout Contractor) 38 Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 30 Sib-Total (Tile & Grout Contractor) 31 Sib-Total (Tile & Grout Contractor) 32 Replace with braided as needed 33 Sib-Total (Tile & Grout Contractor) 34 Sib-Total (Tile & Grout Contractor) 35 Sib-Total (Tile & Grout Contractor) 36 Sib-Total (Tile & Grout Contract	32		15	Service and seal to extend life of materials	\$223 - \$275
GARAGE DOOR CONTRACTOR 33 Sticky/noisy operation, recommend adjustment and/or lubrication 34 Comments: unit has excessive vibration / noise level recommend lubrication 35 Missing required safety sticker/decal next to the operator button 36 Service call to adjust garage door for safe operation 37 Service call to install sticker 38 Sub-Total (Garage Door Contractor) 38 Recommend caulking around the base of all commodes 39 Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 30 Sub-Total (Tile & Grout Contractor) 31 Sub-Total (Tile & Grout Contractor) 32 Sub-Total (Tile & Grout Contractor) 33 Sub-Total (Tile & Grout Contractor) 34 Service call to adjust garage door and repair noted items 35 APPLIANCE CONTRACTOR 36 Recommend caulking around the base of all commodes 37 Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 38 Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 30 Sib-Total (Tile & Grout Contractor) 31 Sib-Total (Tile & Grout Contractor) 32 Replace with braided as needed 33 Sib-Total (Tile & Grout Contractor) 34 Sib-Total (Tile & Grout Contractor) 35 Sib-Total (Tile & Grout Contractor) 36 Sib-Total (Tile & Grout Contractor) 37 Sib-Total (Tile & Grout Contractor) 38 Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 30 Sib-Total (Tile & Grout Contractor) 31 Sib-Total (Tile & Grout Contractor) 32 Replace with braided as needed 33 Sib-Total (Tile & Grout Contractor) 34 Sib-Total (Tile & Grout Contractor) 35 Sib-Total (Tile & Grout Contractor) 36 Sib-Total (Tile & Grout Contract					
Sticky/noisy operation, recommend adjustment and/or lubrication Comments: unit has excessive vibration / noise level recommend lubrication Missing required safety sticker/decal next to the operator button Sub-Total (Garage Door Contractor) **TILE & GROUT CONTRACTOR** Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall **Sub-Total (Tile & Grout Contractor) **Sub-Total (Tile & Gr				Sub-Total (Fireplace/Chimney Contractor)	\$223 - \$275
Sticky/noisy operation, recommend adjustment and/or lubrication Comments: unit has excessive vibration / noise level recommend lubrication Missing required safety sticker/decal next to the operator button Sub-Total (Garage Door Contractor) **TILE & GROUT CONTRACTOR** Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall **Sub-Total (Tile & Grout Contractor) **Sub-Total (Tile & Gr		CAPAGE DOOP CONTRACTOR			
Comments: unit has excessive vibration / noise level recommend lubrication 26 Adjust and repair garage door for safe operation \$167 - \$211 \$211 - \$139 \$22 Service call to install sticker \$32 Service call to install sticker \$33 Sub-Total (Garage Door Contractor) \$3429 - \$539 \$35 Sub-Total (Garage Door Contractor) \$35 Sub-Total (Garage Door Contractor) \$36 Recommend caulking around the base of all commodes \$37 Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall \$38 Sub-Total (Tile & Grout Contractor) \$38 Sub-Total (Tile & Grout Contractor) \$370 - \$468 \$39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from \$30 Install anti-siphon or vacuum break on dishwasher drain line \$31 - \$113	33		14	Service call to adjust garage door and repair noted items	\$151 - \$189
Sub-Total (Garage Door Contractor) \$429 - \$539 TILE & GROUT CONTRACTOR Recommend caulking around the base of all commodes 21 Grouting and caulking as needed throughout \$151 - \$189 37 Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 22 Caulk or grout around commode and shower penetrations \$219 - \$279 Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 22 Replace with braided as needed \$121 - \$151 39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 25 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113	34			, , , , , , , , , , , , , , , , , , , ,	\$167 - \$211
TILE & GROUT CONTRACTOR Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 21 Grouting and caulking as needed throughout \$151 - \$189 22 Caulk or grout around commode and shower penetrations \$219 - \$279 Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 28 Replace with braided as needed \$121 - \$151 29 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113	35	Missing required safety sticker/decal next to the operator button	26	Service call to install sticker	\$111 - \$139
TILE & GROUT CONTRACTOR Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall 21 Grouting and caulking as needed throughout \$151 - \$189 22 Caulk or grout around commode and shower penetrations \$219 - \$279 Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 28 Replace with braided as needed \$121 - \$151 29 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113				Sub Tatal (Carana Base Canterator)	\$420 \$520
Recommend caulking around the base of all commodes Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall Sub-Total (Tile & Grout Contractor) Sayo - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 21 Grouting and caulking as needed throughout \$151 - \$189 \$219 - \$279 \$370 - \$468 22 Replace with braided as needed \$121 - \$151 \$25 Install anti-siphon or vacuum break on dishwasher drain line \$151 - \$189 \$219 - \$279				Sub-Total (Garage Door Contractor)	\$429 - \$539
Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from Sub-Total (Tile & Grout Contractor) \$370 - \$468 22 Replace with braided as needed \$121 - \$151 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from Sub-Total (Tile & Grout Contractor) \$370 - \$468		TILE & GROUT CONTRACTOR			
Sub-Total (Tile & Grout Contractor) \$370 - \$468 APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 22 Replace with braided as needed \$121 - \$151 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 25 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113	36	Recommend caulking around the base of all commodes	21	Grouting and caulking as needed throughout	\$151 - \$189
APPLIANCE CONTRACTOR Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from Span Supplied to Prevent debris and gray water from provided in the prevent debris and gray wa	37	Recommend caulking around all tub/shower faucets and spouts to prevent water entry behind the wall	22	Caulk or grout around commode and shower penetrations	\$219 - \$279
Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 22 Replace with braided as needed 39 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 25 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113				Sub-Total (Tile & Grout Contractor)	\$370 - \$468
Recommend use of stainless steel braided no burst clothes washer water supply lines to reduce chance of water damage 22 Replace with braided as needed \$121 - \$151 Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 25 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113					
Comments: Drain line needs to be better elevated and secured above side inlet of disposal to prevent debris and gray water from 25 Install anti-siphon or vacuum break on dishwasher drain line \$91 - \$113	20		22	Poplace with braided as peeded	\$101 \$454
				•	, , ,
	00		20	model and signor or vacuum broak on dishwasher dialil lille	φυι-ψιιυ
40 Dishwasher not anchored in cabinet \$79 - \$99	40		25	Service call to secure dishwasher	\$79 - \$99



#	ltem	Pg	Action	Range Price
41	Comments: RANGES/COOKTOPS: Range surface has excessive scratches which may/could affect the heat generating. Recommend	d25	Service call to adjust or repair noted items	\$111 - \$139
	repair/service as may needed.			
			Sub-Total (Appliance Contractor)	\$402 - \$502
	CONCRETE CONTRACTOR			
42	Cracked garage slab observed possibly due to movement/settlement		Seal with appropriate caulk and monitor	\$201 - \$253
43	Post tension cable live ends are exposed. Recommend repair before more extensive repairs become needed.	5	Beam patches at cable ends after treating with rust inhibitor to extend life of materials	\$408 - \$518
44	Spalling (i. e., corner pops) at one or more corner(s), Corner spalling is common to slab foundations and does not affect the structural integrity of the foundation.	6	Patch spalling at foundation	\$255 - \$311
45	Observed one or more small cracks in the foundation	6	Beam patch noted areas at foundation, cosmetic repairs only	\$396 - \$504
46	The driveway has settled and has multiple cracks and uneven surfaces	15	Seal cracks to prevent water intrusion	\$250 - \$316
			Sub T-(-) (0(\$4540 \$4000
			Sub-Total (Concrete Contractor)	\$1510 - \$1902
	GUTTER CONTRACTOR			
47	Downspouts need splash blocks at bottoms to prevent soil erosion	8	Install splash blocks where needed	\$141 - \$173
48	Recommend addition of rain gutters to help improve drainage and/or prevent wood rot at the following locations where currently not	8	Install gutters in locations noted	\$712 - \$986
	present			
49	Observed one or more areas of loose gutters		Service to improve flow of water and repair as needed	\$335 - \$413
50	Need general maintenance, cleanout debris / resecure to fascia board/tilt toward drains, seal leaks, etc	9	Downspout needs to be better connected to drain	\$150 - \$190
			Sub-Total (Gutter Contractor)	\$1338 - \$1762
	VENT CONTRACTOR			
51	Comments : some flex duct observed to be routed improperly, not to manufacturers installation instructions. Recommend additional	19	Install smooth metal inside duct to improve safety	\$280 - \$350
	support and/or routing ducts to eliminate snaking drooping or crimping of flex duct more than 1 per foot which adds unnecessary			
	additional resistance.			
			Sub-Total (Vent Contractor)	\$280 - \$ 350
			- Cab Fotal (Vent Contractor)	Ψ200 - Ψ330
	FURTHER ACTION REQUIRED			
52	The floor is not level, possibly due to foundation settlement	12	Structural engineer or foundation specialist needed to inspect	\$746 - \$1036
			structural support and recommend repairs	
			Sub-Total (Further Action Required)	\$746 - \$103 6
			- oub rotal (runtile: Action Required)	ψ1 40 - ψ10 30






#	ltem	Pg	Action	Range Price
53	PEST CONTROL CONTRACTOR Evidence of previous (possibly current) rodent activity in the attic	9 Rodent proof	and service property	\$570 - \$790
		Sub-Total (P	est Control Contractor)	\$570 - \$790

Summary





The Whole Property Estimate Explained: You will notice that if you add every item on your report, the total will never match the Whole Property Estimate total. Why? By using custom calculations we work out not only the individual cost to fix each item, but also the projected cost if ONE contractor per trade were to visit the property and fix all the items at one time. Don't worry, your report is not incorrect and the prices are not meant to match the totals.

TOTAL ESTIMATE:

\$16,908 - \$22,256

Thank you for choosing Repair Pricer

About Repair Pricer

Repair Pricer is the industry standard for converting inspection reports into accurate repair estimates during the complex property purchasing process, enabling all parties to act quickly and confidently during a critical period. Repair Pricer saves time and reduces stress for everyone when it matters most. To learn more about Repair Pricer, visit www.repairpricer.com



It is important you understand that the service provided by RepairPricer.com is purely for estimation and negotiation purposes. We do not guarantee that the prices we estimate for repairs on your report are the same that you will encur up paying for that specific repair. Our pricing is based on the average cost for a similar repair in your area, and due to unknown factors or underlying issues that we are not privy to, actual repair cost may be substantially higher.