

Industrial Maintenance SOP - Pump P101

Equipment: Pump P101
Location: Process Area A

Shutdown Procedure

1. Inform control room before shutdown.
2. Switch off electrical power supply.
3. Close inlet valve completely.
4. Close outlet valve.
5. Drain remaining pressure from the system.
6. Verify lockout/tagout procedure.

Preventive Maintenance

- Inspect bearings every 30 days.
- Check lubrication levels weekly.
- Replace worn seals immediately.
- Record maintenance activities in maintenance log.

Safety Requirements

- Wear PPE at all times.
- Follow Factory Act safety guidelines.
- Maintain inspection records.
- Conduct fire safety drills quarterly.