

Field Trial Report

Neendakara and Munambam, October 2025 to March 2026

Design

220 vessels across two harbours were fitted and observed for six months. Usage, message volume, failure events and owner interviews were recorded throughout.

Usage

Terminals were powered on for 91 percent of fishing days. Catch logging was used on 78 percent of trips. Weather warnings were acknowledged on 94 percent of pushes.

Events

Eleven distress activations, of which two were accidental and nine were genuine. Of the nine, four involved engine failure, three involved a man overboard recovered safely, and two involved sudden weather.

Failures

Five terminal failures, of which three were antenna cable damage from crew activity and two were water ingress through a wheelhouse mount installed against guidance. All five were replaced under warranty and the mount guidance was rewritten.

Owner interviews

Asked what they would pay for if the subsidy disappeared, 14 of 22 interviewed owners named the catch log first and the distress button second. That finding is the reason the product roadmap now leads with fleet reporting.