





Reasons for Jitter:

- 1. Unoptimized code
- 2. Errors in the hardware clock
- 3. Other environmental conditions that effect the hardware clock
- 4. Variations in the power supply

Ways to improve jitter:

- 1. Optimize the code
- 2. Use more machine friendly programming language like C to improve timestamping
- 3. Use better performing hardware clocks
- 4. More stable conditions for the clock (environmental and power supply)